SURVEY & REMONUMENTATION

APR 0 5 1996

COMMISSION

OTTAWA COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Ottawa (County)

RECORDED

95 NOV 15 PM 2:08

REGISTER OF DEEDS OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

		Located In:		Corner Code #
1. Public Land Survey		T5N	R16W	I-13 SW Cor
		T____	R____	Sec. 35
		T____	R____	Park Twp.
		T____	R____	
2. Property Controlling	S____	T____	R____	
in Section	S____	T____	R____	
3. Miscellaneous	S____	T____	R____	
Property in Sec.	S____	T____	R____	

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Steven Lampen, in a field survey on October 12 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I-13
GLO Survey Notes
1832 - Surveyor, Lucius Lyon
Set Post
14" Maple N 82°E 47 links
8" W. Ash N 42°W 40 links

I-13
Recorded in Liber 2, Page 21
Found 3/4" Iron Pipe
Light Pole WNW 65.95'
Power Pole NE 45.82'
Light Pole SE 56.40'
Power Pole SW 94.52'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-13
Found 1/2" pipe in well point in monument box and accepted it as a careful and faithful perpetuation of the position of the original corner

P.A. 345 OTTAWA COUNTY
PEER APPROVED 10/23/95

Wesley D. Nedewald
PDM

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-13
Set O.C. Remon Cap & Iron

NW cor garage found	AZ.205°13'	76.18'
Set O.C. Reom Tag & Nail NE side guy pole	AZ.311°08'	67.16'
NW cor garage foundation	AZ.128°20'	176.89'
SW cor brick wall, school	AZ.27°54'	232.37'
Allegan County corner	AZ.270°26'49"	107.12'
SW cor Harrington 4th Add Mac Park Grove	AZ.355°09'	5.95'
SE cor Harrington & Vandenberg Bros Sub	AZ.355°09'	5.95'

STATE OF MICHIGAN
STEVEN LAMPEN
LAND SURVEYOR
NO. 37279
REGISTERED LAND SURVEYOR

Signed by Steven Lampen Date October 23, 1995

Surveyor's Michigan License No. 37279

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1976
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993