SURVEY & REMONUMENTATION

APR 0 5 1996

COMMISSION

OTTAWA COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Ottawa (County)

	Located In:	Corner Code #
1. Public Land Survey	T8N R13W	A-6
	T___ R___	W 1/4 cor. Sec.
	T___ R___	18, Wright Twp.
	T___ R___	
2. Property Controlling	S___ T___ R___	Common corner
in Section	S___ T___ R___	w/ M-6
3. Miscellaneous	S___ T___ R___	Polkton Twp.
Property in Sec.	S___ T___ R___	

RECORDED
95 NOV 29 PM 1:34
REGISTER OF DEEDS
OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Steven Lampen, in a field survey on November 15 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-6
Survey recorded L 3-P 728
Found cross in pavement
6" Apple E 38.14'
Power pole SW 45.45'
15" Maple SE 98.25'

LCRC L 3-P 387
Sept. 5, 1979
Set P.K. nail from ties
Nail in side 6" Apple E 38.30'
Nail in side power pole SW 45.45'
Nail in side 15" Maple SE 98.25'
On centerline 9' wide concrete road
Fence and tree line E & W
(Recorded as M-6, T8N, R14W)

LCRC L 6-P 28
Jan. 3, 1990
Found P.K. set cast iron monument
6" Apple E 38.28'
15" Maple SE 98.25'
Power pole SW 45.47'
(Recorded M-6, T8N, R14W)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-6
Found cast iron monument. This position not established by original government surveyors. This monument is accepted as the best available evidence of the position of the corner.

Found nail & washer in N side 14" Apple S 83° E 38.28'
6" Apple E 38.28'
15" Maple SE 98.25'
Power pole SW 45.47'

P.A. 345 OTTAWA COUNTY
PEER APPROVED 11/20/95
Gordon D. Nedeau
GDN

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-6
Cast iron monument
Set O. C. Remonumentation tag & nail in S side 14" Apple S 83° E 38.34'
Set O. C. Remon. tag & nail in W side 16" Maple S 15° E 97.73'
Set O. C. Remon. tag & nail in SE side power pole S 64° W 45.49'
Set O. C. Remon. tag & nail side power pole N 38° E 182.37'

STATE OF MICHIGAN
STEVEN LAMPEN
LAND SURVEYOR
NO. 37279
REGISTERED LAND SURVEYOR

Signed by Steven Lampen Date November 17, 1995

Surveyor's Michigan License No. 37279

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197
REVISED MAY 14, 197
REVISED JAN., 198
ADAPTED FOR WORD PROCESSING MARCH, 199