LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF–:	LOCATED IN–:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 24 N., R. 9 W.	E-3; F-2
2. PROPERTY CONTROLLING IN SECTION 4	T. 24 N., R. 9 W.	5; 6
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. S., R. _____ E. W.	
4. LOT NO. _____ , RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on October 10, 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~A. Description of original monument and accessories and/or subsequent restoration:~~

C. (continued)

6

Set 1"x36" pipe & cedar post w/loc. tag

4" R. Pine	S37°E	33.3
20" Oak	S83°W	84.3
16" Oak	N29°W	66.6

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-3 Found and accepted "T" iron with RLS cap #6525 (T. Schweigert) as restored by him from old US-131 plans (1920's±). M.D.S.H. also tied this corner in 1955.

F-2 Established center of Section at intersection of ¼ lines. Corner fell in old N-S fence, with corner fence post (fence south and west) 24' north.

5 Established SW corner of fractional NW¼ of fractional NE¼ (per GLO plat) per standard B.L.M. instructions.

6 Established corner (center of NE¼ per GLO plat) per standard B.L.M. instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-3

Fd. "T" iron & added std. Wexford Co. mon. & cedar post

14" Maple	N20°E	27.82
10" Maple	N43°W	39.47
12" B.Cherry	S74°W	56.48

Ctr. old B.top hwy. Due E 37.0

F-2

Set 1¼"x36" pipe & cedar post w/loc. tag

12" Oak	S66°W	14.1
9" R. Pine	N16°W	47.3
14" Oak	S64°E	49.1

Ctr. US-131 Due W 151.2

5

Set 1"x36" pipe

10" R. Pine	S47°W	85.42
10" R. Pine	N10°E	97.65
P. Pole	S33°E	92.87
Ctr. US-131	Due E	20.6

Set cedar post w/loc. tag Due W 33

SIGNED BY Carl F. Roser 3-4-75 DATE _____

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ (CHIEF OF SURVEY PARTY) DATE _____

APPROVED AND SIGNED BY _____ (MICHIGAN REGISTERED LAND SURVEYOR) DATE _____

(SEAL)

LIBERTY TOWNSHIP
WEXFORD COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Form No. MLM736
DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS