

United States Department of Agriculture

Barnett Surveying Inc.

474 S. Branch Rd.
Branch, Michigan 49402
Ph: 616-898-2234 or 1-800-632-0167

SURVEY REPORT

05/11/92

The 1/4 corner common to Sections 12 and 13, T20N, R18W is a 5" \times 5' concrete monument placed by R. A. Griffen.

To verify the location of this monument we located the irons as shown on the plat of IDEAL PARK at the West end of St. James Ave., St. Louis Ave. and Augusta Ave. and the iron on the Southeast end of Ravine Rd. The distances as shown on the plat and our field measurements indicate that R. A. Griffen monumented the North 1/4 corner of Section 13 as shown on said plat. This corner has been used by Barnett and Hays Inc. in a survey done in 1985 in Section 13 and by Ross Surveys in a survey done in 1982 in Section 12 and is the best available evidence of the original corner position.

The Northeast corner of Section 13.

In 1935 E. Swan, Chief of Party with the Michigan State Highway Department set an axle shaft and 4" pine post 2640 feet South of the 1/4 corner on the East side of Section 12 and 3080.3 ft. East of the M. C. corner common to Sections 12 and 13. In 1965 R.A. Griffen replaced the axle shaft with a 5" x 5' concrete monument. This monument is still in the same location at this time. This location has been used by Barnett and Hays Inc. in a survey done in 1985 in Section 13 and by Ross Surveys in a survey done in 1982 in Section 12. The Ross survey shown the corner to be 2638.01 feet South of the 1/4 corner on the East side of Section 12. The M.C. corner between Sections 12 and 13 was not found.

At some unknown time it would appear that someone thought that the iron pipe found on the East side of the plat of IDEAL PARK may be the East 1/16 corner between Sections 12 and 13. The distance between this iron and the 1/4 corner between Sections 12 and 13 was doubled in and a iron pipe was set South 51 degrees East 191.11 feet from the Northeast corner of Section 13.

The Southeast corner of Section 13 was established by single proportionate measurement between the U.S.F.S. concrete monument at the Southeast corner of Section 24 and the U.S.F.S. concrete monument at the Northeast corner of Section 13.

The original G.L.O. creek calls at the Southeast corner of Section 13 placed the post 351 feet East of the creek, and 528 feet South of the creek.

Barnett Surveying Inc.

474 S. Branch Rd.
Branch, Michigan 49402
Ph: 616-898-2234 or 1-800-632-0167

The single proportionate location of the Southeast corner of Section 13 gives a modern day location of 345 feet east of the creek and 530 feet South of the creek.

If the existing pipe near the Northeast corner of Section 13 was used as the corner the creek call at the Southeast corner of Section 13 would be up the East bank of the creek about 80 feet.

Based on the above information I feel that the U.S.F.S. concrete monument at the Northeast corner of Section 13 is and has been accepted as the best available evidence of the original corner position.

Sammy S. Barnett L.S. President




LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Mason Located In:		
7. Public Land Survey	9W <u>M-7 & M-6</u>	
T R - T R -		
T R T R 2. Property Controlling S T R in Section S T R		
7 R 2 2. Property Controlling S T R 2 in Section S T R		
in Section S T R _		
B. Miscellaneous S T R _		Register of Deeds Stamp & File Number
8. Miscellaneous S T R _ Property in Sec. S T R _		
Lot No, Recorded Plat		A B C D E F G H I J K L I
5. Private Claims	The second secon	
		3
	- 00	4-7-8-19-11-12
n, <u>Sammy S Barnett</u> , in a field survey on do hereby certify that under requirements of P.A. 74, Michi		ned 6 18 17 16 15 14 13
do hereby certify that under requirements of P.A. 74, Michin fines 1 and 2 above were in conformance with regular	tions and rules therefore as required in	the and 7
current manual of survey instructions of the United State	s corner points mentioned in lines 3, 4 a	nd 5 8 19 20 21 22 23 24
Management or by a decree of a Court of Law and/or that the above were in conformance with the rules of the Michigan Court of Law; established, re-established, monument	Board of Land Surveyors or by a Decree	of a g
Court of Law; established, re-established, monuments	de le	10 30 29 28 27 26 25
NOTE: Not more than 4 corners, all in the same t	own and range, may be recorded	12 31 32 33 34 35 36
on this certificate.		13
A. Description of original monument and accessor	ries and/or subsequent restoration:	common to sec. 13 T20N R18W & Sec.
M-7 Sec. cor. common to Sec. 13 & 2	4 TZON, M-6 1/4 COI:	
R18W & Sec. 18 & 19 T20N, R17W Post placed by John Mullet in 1838	Post placed b	y John Mullet in 1838 survey
	S70°W 23 1ks	10" Hemlock
S65°W 18 1ks. 14" Hemlock N57°W 57 1ks 16" Beech	N45°W 39 1ks	
3. Description of corner evidence found and/or me	ethod applied in restoring or reesta	on to Sec. 13 T20N R18W & Sec.
M-7Sec. cor. common to Sec. 13 & 24	18 TOOM R17W	
R18W & Sec. 18 & 19 T20N, R17W Found Nothing, Cor. established by s	ingle Found nothing	, cor. established by single
roportionate measurement between u	e SE proportionate	measurement between the SE cor. the SE cor. Sec. 12.
or Sec. 24 and the SE cor. Sec 12	Sec. 15 and c	on 16" R. Pine, approximate
LO creek calls E. 351; measured 345 N. 528' measured 530		64
		SAMMY S.
		BARNETT LAND SURVEYOR
		LAND SORVETOR
		16923
Description of monument for corner and accesss	ories established to perpetuate loc	cating the position of the compr
7 Soc cor common to Sec. 13 & 24		
18W & Sec. 18 & 19 T2ON, R1/W	18 T20N R17W	Placed a 2" x 30" stainless steel mped cap, monument is accepted
placed a 2" x 30" stainless steel pi with stamped cap, monument is accept	pe pipe with sta	vailable evidence of the original
is the best available evidence of th	e corner.	
original corner.	N86°W 29.41'	15" Red Maple
68°E 29.85' 5" Red Maple	S50°E 18.82' S23°W 21.14'	4" Ked Mapie 4" Red Oak
136°E 8.55' 7" Beech 145°W 33.47' 5" Beech	S74 W 60.00'+	- 16" R. Pine no spike, blaze or p
South 1.0' Carsonite post	West 1.0' Car	
the state of the s		
gned by Sam Barnets	Date	05/05/92
urveyor's Michigan License No.	16923	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197 REVISED MAY 14, 197
		REVISED JAN., 198

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	, mild vedaliewe	ent of Act 74, Mich. P.A. 19	70	
corners in	Located In:	Corner Code ##		
Mison (County)		Corner Code #		
Public Land Survey	TR			
y. Public Land	T R			
	<u> </u>			
2. Property Controlling	s 13 T 20N R 18W	10 & 12		
in Section	STR	10 4 12		
3. Miscellaneous		F	Register of Deeds Stamp & F	ile Number
Property in Sec.	S T R			
1 Lot No	Recorded Plat		— ABCDEFG	HIJKLA
5. Private Claims			- 2 1	1 1 1 -
			3 3 3 1	
			4 ├─┼┼┊┼┼┊┼┤	0-11-12-
Sammy S Barnett	, in a field survey onMarch_	19 92	5	
do hereby certify that under r	equirements of P.A. 74, Michigan P.A. of 19		6 18 17 16 1	
			8 19 20 21 2	2 23 24
Management or by a decree of	of a Court of Law and/or that the corner poin	od Surveyors or by a Decree of a	• 	++++
Court of Law; established,	with the rules of the Michigan Board of Lan- re-established, monumented, re-monu-	mented, recovered, found as	10 30 29 28 2	7-26-25
to be a seed bolour	corners, all in the same town and ra		"}	35 36
NOTE: Not more than 4	de.		12 31 32 33 3	
	al monument and accessories and/or	subsequent restoration:	to moon P18W	
A. Description of origina	on W. line Sec 13 T20N	12 C. S. 1/16 cor.	. sec 13 T20N R18W	
R18W	a have made asked by the	the form the management of	eiginal survey	
	estantian facilities	Cor. not set in or	iginal Salvel	
Cor. not set in c	original survey			
			o corner:	
n Description of corner	evidence found and/or method applie	ed in restoring or reestablishin	12 m20N P18W	
10 S. 1/16 cor on	W. line Sec 13 T20N			- TITTE
R18W	post set in 1985 survey	Found 1/2" rebar	set in 1985 survey	F MICHIGAN
by. S. Barnett no	witnesses	S. Barnett no with	lesses	041
by. S. Darness			42 / 8	ARNETT
			A LAND	SURVEYOR
			R	NO.
			B.E.	16923
			EAFO	LAND SUND
		* 1	C the corner	LAND
	ent for corner and accessories establ	ished to perpetuate locating t		
C. Description of monum	W. line Sec 13 T20N	Replaced 1/2" reb	ar with 5/8" x 24" record not established	epar with
R18W Replaced fen	W. line Sec 13 T20N ce post with 5/8" x 24" d cap, This cor not a Alumi ininal GLO survey, This	stamped Cap. IIIIs	COL ic	accepted
rebar with stampe	ininal GLO survey, This	original GLO Surve	ey. This monument is faithful determination orner.	on of the
established in or	had as a careful and	tition of the CC	rner.	
faithful determin	ation of the position	S28 W 18.67 10" F	ed Oak	
of the corner. S30 W 10.65 16"		CAE E 36 78' 5" ST	igai riapic	
-07 ⁰ E 10 70'76" 5	. Mapie	West 1.0' Carsonit	e post	
26 90 65" H	emtock			
East 1.0' Carsoni North 10.02' Fence		pate	05/05/92	
North 10.02 Fence Signed by	16923		OVED BY MICHIGAN STATE BOARD OF LAND SU	JRVEYORS, JAN. 28, 1971
Surveyor's Michigan Licen	se No	FORM APPR	OVED BY MICHIGAN STATE BUARD OF EARD OF	REVISED MAY 14, 1975 REVISED JAN., 1983
Surveyor a Michigan Live		TERRY KESSE Updated Wik	2003	
		Updated Wit	,	



Scanned with CamScanner

