



DELIVERED TO NEWAYGO CO
02/06/2015 12:28:34 PM

2014 Newaygo County Remonumentation Project

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Newaygo
(County)

Located in: Corner Code #

VOL. 8

80

1. Public Land Survey

T14N R11W
T N R W
T N R W
T N R W
T N R W
T N R W
T N R W
T N R W

I-5

2. Property Controlling
in Section S
3. Miscellaneous
Property in Sec. S



STEWART K SANDERS
NEWAYGO COUNTY REGISTER OF DEEDS
RECEIVED AND RECORDED
02/06/2015 12:30:23 PM

4. Lot No _____ Recorded Plat _____

5. Private Claims _____

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, Norman L. Ochs, in a field survey on December 19, 2014, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below

Note: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Section Corner common to Sections 10, 11, 14 and 15, T14N R11W, Goodwell Township

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

GLO
J H Mullett, November 13, 1837
Set post corner
#1 12" Pine S36°E 30 links (19.8')
#2 12" Pine N61°W 21 links (13.86')

Daniel E. Schripsema, R.L.S.# 24617
Job No. 98161 November 20, 1998
Found a 5/8" Iron in 1 1/2" Pipe
#3 8" Oak N89°W 27.60'
#4 10" Oak N03°E 9.78'
#5 1" Oak N74°E 10.36'
#6 12" Oak S42°E 17.82'

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

I found a 1 1/4" x 20" Well Point 4"± below grade that was raised with a 5/8" x 6" Rerod to 2"± above grade. No apparent occupation to the North, South, East and West The centerline of an East and West sand road is 90°± South. The condition of the witnesses are as follows: #1 and #2 gone, #3 thru #6 in good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

I removed both the Well Point and the Rerod and set a 4" diameter Harrison Cast Iron Monument 20" long marked "County Surveyor #22439", 4"± above grade as a substantial marker for the corner and is accepted as a careful and faithful reestablishment of the position of the original Section Corner

#3 10" Black Oak N89°W 27.59'
#4 10" White Oak N7°E 9.82'
#5 12" Black Oak N78°E 10.43'
#6 10" Black Oak S42°E 17.81'
Found nail in North side
Found nail in West side
Set 40d nail with tag, above overgrown nail in North side
Found nail in Southwest side

Signed by Norman L. Ochs Date February 6, 2015
Norman L. Ochs

Surveyor's Michigan License No 22439

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971
Revised May 14, 1975
Revised Jan , 1983

Approved by Peer Review Group on December 8, 2014
Norman L. Ochs, County Representative

Norman L. Ochs

