

SURVEY &  
REMONUMENTATION

MAR 16 2005

SECTION

A. Continued

Ralph Smith RLS # 3421

April 19, 1956 Land Corner card  
½" Pipe

#3 24" Black Oak N50°W 10.5'

#4 14" Black Oak N70°E 35.2'

#5 14" Black Oak S30°E 41.6'

Robert A Griffin RLS # 13584

LCRC # 112, April 1963

Replaced ¾" Pipe with a round 6" diameter concrete post with 3" diameter brass cap

#6 Stone with "X" cut in top N46°E 103.56'

#4 15" Red Oak N60°E 35.60' 10" dock spike in NW side

#5 16" Red Oak S32°E 42.15' 10" dock spike in NE

#3 24" Red Oak N46°W 11.25' 10" dock spike in SW side

Consumers Power Co., E. McCombs RLS # 10696

Drawing # S-F18317, August 1984

#6 Stone with "X" cut in top N46°E 103.5'

#4 15" Red Oak N60°E 35.6 to spike

#5 16" Red Oak S32°E 42.15' to spike

#3 24" Red Oak N46°W 11.25' to spike

James H Miller RLS # 27456

Job # 9403.644, Liber 359, page 5793

May 24, 1994

Found 6" concrete post with brass tablet stamped "T15N-R11W, ¼, S14 S13 1963"

#6 Stone with "X" cut in top N46°E 103.50'

#4 18" Red Oak N60°E 35.60' found spike in NW side

#5 18" Red Oak S32°E 42.15' found spike in NE side

#3 28" Red Oak N46°W 11.25' found spike in SW side