

**SURVEY &
REMONSTRATION**

MAR 13 2002

A. Description (cont.)

William M. Jacques, (County Surveyor)
1904 Book 8, Pages 74-75
Pine Stake with broken glass and dishes around corner
December 20, 1905 Book 8, Page 36
#4 30" Pine Stump S43°15'W 40 links (26.40')

Lyle S. Shepard RLS #503.

April 17, 1934 Book B, Page 86

Iron

Witness Book #1, Page 7

Iron

#5 24" Pine Stump N45°W 36.90'

#6 36" Pine Stump S40°W 65.50'

#7 18" Black Oak S20°E 93.70'

Newaygo County Road Commission Sheet

±1950's

½" Iron

#8 Power Pole S58°E 71.70'

#9 8" Maple N50°W 52.30'

#7 28" Black Oak S14°E 92.90'

Norman L. Ochs RLS #22439

February 1980

Found ¾" Pipe

#10 Power Pole N60°E 62.94' Nail in North side

#6 36" Pine Stump S40°W 65.50'

#8 Power Pole S58°E 71.64' Nail in North side

#9 8" Maple Stump N50°W 52.30'

Keller Engineering & Land Surveys

August 4, 1992

Found Iron

#11 16" White Oak N22°W 71.15'

#10 Power Pole N70°E 63.44' PK in Southerly side

#8 Power Pole S56°E 72.25' PK in Southerly side

#12 16" Maple S29°W 74.41'

Norman L. Oaks RLS #22439

May 17, 2000 Drawing #00057B

Found ¾" Iron Pipe

#11 16" White Oak N22°W 71.15'

#10 Power Pole N70°E 63.44' PK in Southerly side

#8 Power Pole S56°E 72.25' PK in Southerly side

#12 16" Maple S29°W 74.41'

January 2, 2001 Drawing #00294AC & M

Found ¾" Plinch Pipe

#11 16" White Oak N22°W 71.15'

#10 Power Pole N70°E 63.44' PK in Southerly side

#8 Power Pole S56°E 72.25' PK in Southerly side

#12 16" Maple S29°W 74.41'