

**SURVEY &
REMONUMENTATION**

AUG 20 2003

SECTION

**LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

OSCODA
(County)

Located In: _____ Corner Code # _____

Libor 6 lg/29

FILED

At S. S. o'clock A. M.
Date 8-15- 2003.

Clerk/Register of Deeds
Oscoda County, Michigan

Register of Deeds Stamp & File Number

- 1. Public Land Survey T 26N R 1E _____
T _____ R _____
T _____ R _____
T _____ R _____
T _____ R _____
- 2. Property Controlling _____
in Section S _____
- 3. Miscellaneous _____
Property in Sec. S _____

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

I, Marvin E. Myers, in a field survey on June 9, 2003, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

A-6 W 1/4 CORNER SECTION 18, T26N, R1E

- 1839 GLO Clason, DS 1884 Randall, CS 1937 USGLO Veal, CE
- Not set Indicates corner Set 2" Pipe with Brass cap by Prop. Dist.
- 4" Balsam N44°15'E 22 lks
- 10" Cedar S80°30'E 33 lks

- 1967 USFS R. Griffin #13584
- Fd USGLO Pipe & Cap
- 14" Cedar N25°E 26.86
- 11" Cedar S80°30'E 22.16
- Cedar Post North 1.6

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-6 W 1/4 CORNER SECTION 18, T26N, R1E

Found USGLO 2" Pipe with brass cap; found 14" Cedar N25°E 26.86; found 11" Cedar S80°30'E 22.16; found Cedar Post North 1.6

Accepted pipe as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-6 W 1/4 CORNER SECTION 18, T26N, R1E

- Mon - USGLO 2" Pipe with brass cap
- Wit: 8" Cedar N86°W 25.55
- 14" Cedar N25°E 26.86
- 11" Cedar S80°30'E 22.16
- Cedar Post North 1.6

APPROVED

County Remonumentation
Peer Review Group

NCC 24 JULY 03



Marvin E. Myers

Signed by _____ Date July 12, 2003

Surveyor's Michigan License No. 31600