

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

Found USGLO 1" pipe with 2 1/2" dia. brass cap projecting 5" above ground with Cedar Location marker post alongside (brass cap appears to have been shot, but still in good shape), corner is 35'± East of centerline of Coyote Drive and 20'± South of centerline of USFS road number 4477; found 8" Black Oak (now 14" stump) S04°15'W 25.74'; found 7" Red Maple (now 14" twin Red maple) N78°E 9.4'.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

Mon - USGLO 1" Pipe with 2 1/2" dia. brass cap left in place

Wit:	N19°39'E	52.83	Set nail and tag in East side 5" Black Oak
	N87°22'W	82.32	Set nail and tag in North side 8" White Birch
	S44°57'W	35.55	Set nail and tag in East side Road signpost (Coyote Drive)
	S04°15'W	25.74	Set nail and tag in top of 14" Black Oak stump (fresh cut for firewood)

Date of Observation	Latitude	Longitude	Datum and Adjustment Year	Epoch Date
5-21-2020	N44°34'45.46"	W084°16'51.20"	NAD 83 2011	2010

Coordinate were determined directly from a Continuously Operating Reference Station (CORS).

The Latitude and Longitude reported hereon, to the nearest estimated accuracy of 0.01 seconds of arc, are to be used as a navigational aid to the approximate location of the corner and shall not be used to reestablish the position of the corner or relied upon for use in establishing boundaries.

Cole A Sorenson

August 4, 2020

Cole A Sorenson, PS

Date

Professional Surveyor's License No.: 59056

Rowe Professional Services Company, 2342 Industrial St., Suite A, Grayling, Michigan 49738



I, Jeremy R Card, PS, state that the corner(s) identified and described hereon and perpetuated or monumented as described in Parts A, B, and C above was presented to and reviewed by the Peer Review Group on July 28, 2020 and is accepted for filing in the Oscoda County Remonumentation Program.

Jeremy R Card

8-21-2020

Jeremy R Card, PS

Date

Professional Surveyor's License No.: 47947

