

REMONUMENTATION

MAY 18 1997

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 003 PAGE 04 | 3

For corners in

Lake _____ (County)

Located in: _____ Corner Code: #8

RECORDED
LAKE COUNTY, MI.
Dec 16 10 27 AM '96
REGISTER OF DEEDS

Spencer H. Dickson

Register of Deeds Stamp & File Number

- 1. Public Land Survey
18N T R 14W C-8
- 2. Property Controlling in Section S R
- 3. Miscellaneous Property in Sec. S R

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

Robert L. Wetherell _____ November 12, 1996

I, _____, in a field survey on _____, 19____ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
C-8 - 1/4 Corner common to Sections 19 & 20, T18N, R14W, Lake Co., MI.

- 1838 - S. Sibley, G.L.O.
- #1 - 8" Cedar N37°W 9 Links
- #2 - 6" Cedar S42°E 17 Links
- 1951 - George Blass - L.S. 5489
- Found "U" shaped iron bar and remains of wood stake. Local resident, Mr. Stevenson, told him this had been used for at least 40 years. Raised with 1" pipe bed rail.
- #3 - P. Pole N54°E 36.40'
- #4 - N. Guy Anchor N23°E 69.95'

(SEE OVER FOR CONTINUATION OF "A")

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-8 - 1/4 Corner common to Sections 19 & 20, T18N, R14W, Lake Co., MI.

I found 5" x 60" U.S.F.S. Monument projecting 2.5 feet above the ground. I lowered the monument to 1.0 feet above the ground. Found pipe bed rail along side of monument.

Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Gone, #4 Found in good condition, #5 Found in good condition.

PAID BY _____
DATE 12-12-96
R.L.W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-8 - 1/4 Corner common to Sections 19 & 20, T18N, R14W, Lake Co., MI.

I accepted the 5" x 60" Monument as a substantial marker for the corner, and is accepted as a careful and faithful re-establishment of the position of the original corner.

- 4" Post West 0.84'
- 2" Pipe Guy Anchor N30°E 70.08' (#4)
- P. Pole N46°E 74.12' (60d in S.E. side) New Pole
- 6" R. Pine S55°E 82.81' (60d in N.E. side)
- P. Pole S06°E 228.68' (60d in W. side)

Signed by *Robert L. Wetherell* Date 12-13-1996

Surveyor's Michigan License No. 24624

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

