

State of Michigan Remonumentation Program  
For Presque Isle County

PRESQUE ISLE COUNTY  
RECORDED

91 AUG 23 AM 10:10

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

PRESQUE ISLE  
(County)

Located in:

Corner Code #

1. Public Land Survey

T 36N R 2E M-12

T R

T R

T R

T R

T R

T R

T R

2. Property Controlling

S R

S R

S R

S R

3. Miscellaneous

T R

T R

T R

Property in Sec.

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

*Jenette M. Slomd*  
REGISTER OF DEEDS

LIBER 310 PAGE 929

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2							
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, Ronald Bischer, in a field survey on May 2, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

1856 Resurvey - GLO Notes

Set Wood Post

Hemlock 18" S67½°W 14½ links

Hemlock 14" N32°W 5 links

10-18-79 - Ronald R. Bischer

Set ½" Rod by Single proportion.

N43°W 25.73', 10" Maple

N56°E 12.96', 5" Maple

S58°E 33.71', 13" Birch

10-30-79 - Ronald R. Bischer

½" Rod

N43°W 25.73', 10" Maple

N56°E 12.96', 5" Maple

S58°E 33.71', 13" Birch

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found ½" Rod and Cap #15410

N53°E 12.96', 7" Maple

S58°E 33.71', 18" White birch


N43°W 25.73', 10" Maple

found stump w/foot blaze

**SURVEY &  
REMONUMENTATION**

SEP 09 1994

COMMISSION \*



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

½" Rod and Cap #15410

N53°E 12.96', 7" Maple

S58°E 33.71', 18" White birch

S87°W 16.09', 5" Fir

N67°W 25.24', 5" Fir

Witness tags w/nails used.

Ratified by Peer Group  
in accordance with P.A. 345

Chairman *Delmer E. Porter*

Date July 29, 1994

Signed by Ronald R. Bischer

Date July 20, 1994

Surveyor's Michigan License No. 22428