FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -: LOCATED IN -: C	ORNER CODE NUMBER
1. PUBLIC LAND SURVEY T. 33 N. R. 3 W. J-	3, K-3, K-4
2. PROPERTY CONTROLL. ING IN SECTION, T	4/
PROPERTY IN SECTION T. N. S., R. W. P. C.	Y E A R S O F EXCELLENCE
diede in the control of the control	C.I. Robinson &
4. LDI NO, RECORDED PLAT	Assoc., Inc.
13, PRIVATE CLAIMS	1.6 1989
DISTRICT  T. Gerald R. McKelvey do hereby certify that the corner points mentioned in lines 1 and 2 above (identified	t under requirements of P.A. 74, Michigan P.A. of 1970  I with circles on index code diagram over) were in
restored as expressed below and in conformance with regulation of survey instructions of the United States Department of the Incourt of law. Furthermore, that the corner points mention	established, monumented, re-monumented, recovered on and rules therefore as required in the current manual nterior, Bureau of Land Management or by a decree of a ned in lines 3,4 and 5 above were, in a field survey of ished or re-established as expressed below and in consisted or re-established as expressed below and in consisted or re-established as expressed below.
A. Description of original monument and accessories and/or su	
3-3 DNR FIELD NOTES: Found Subdivisi	on Monument - cement post
K-3 DNR FIELD NOTES: Found 2" x 2" W Silver Lake Sub. No. 1" tied to c	lood Post - ALSO "Donners orner as well as Sub. No. 2.
K-4 LCR Orlando Doyle L. "A" Page 65; intersection fence 19' E and 21' shown as Monument Point in "Donne	Set 1" Pipe at fence
B. Description of corner evidence found and/or method applied	in restoring or re-establishing corner:
U-3 Found 1" Iron Rod at Corner - Pos Measurements for survey in area.	ition fits previous DNR
K-3 Found PK Nail at Corner and verif	ied against subdivision ties.
K-A Found Concrete Monument at corner subdivision ties.	and verified against
C. Description of monument for corner and accessories establi-	shed to perpetuate locating the position of the corner:
De3 Left 1" Iron Rod in Corner as four PK in Guy Pole N24°W 30.85'; PK in Michigan Consolidated Gas Marker S	n Fence Doet SETT 62 421.
K-3 Set ½" x 18" Iron Rod at Corner; FPK in P. Pole South 34.44'; PK in 3/4" Iron Pipe South 85.00'	12" Aspen S30"E 24.98';
K-4 Left Concrete Monument at Corner; Tag in Fence Post East 30.16'; Tag 18.00'; Tag in 6" Mult. Maple S45	Tag in Fence Post West 17.48'; in 6" Mult. Maple N50°E E 32.77'.
SIGNED BY Guald K. McKelly	DATE September 9, 1977
SURVEYOR'S MICHIGAN REGISTRATION NO. 19001	
FOR STATE AND UNITED STATES AGENCIES:	DATE THE TOTAL OF MICHIGAN
APPROVED AND SIGNED BY. MICHIGAN REGISTERED LAND SURVE	MCKELVEY *
	DATE SURVEYOR OF HICKORY SURVEYOR NO. 19001
SURVEYOR'S MICHIGAN REGISTRATION NO.	ED BY MICHIGAN STATE BOARD OF CHANNING
FORM APPROVIDENCE BOOK SOCIETY OF THE PROVIDENCE BOOK STRIBUTED	ED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28. 1971 BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

of

## LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORN	ERS OF -:	LOCATED IN-:	CORNER CODE MUMBER	
1. PUBLIC	LAND SURVEY	T. 33 N. R. 3 W.		1972 - 1999
2. PROPEI	RTY CONTROLL- NG IN SECTION———	,T N. E E. W.		27
3. MISCELI PROPER	LANEOUS TTY IN SECTION	,T, S., R W.		YEARS OF EXCELLENCE
18 18 18	, RECOR			C.I. Robinson & Assoc., Inc.
6 12 1 3 C 2 3 1 1	CLAIMS			DECUSED OF DEEDS STAMP AN
				REGISTER OF DEEDS STAMP AN
the corner field surve restored as of survey in court of la	points mentioned in livy on	ines 1 and 2 above (identi- ————————————————————————————————————	fied with circles on index re-established, monumente tions and rules therefore as Interior, Bureau of Land Mined in lines 3,4 and 5 and blished or re-established a	P.A. 74, Michigan P.A. of 19 code diagram - over) were, id, re-monumented, recovered required in the current man fanagement or by a decree obove were, in a field survey a expressed below and in cost or, by a Decree of a Court
A. Descript	ion of original monumer	nt and accessories and/or	subsequent restoration:	The property
3-4	Not a GLO Cor	ner - No old Reco	rds found.	
1-4	on North side	of E-W Road - al	gm 111; Hemlock f so DNR Field Note m fence corner No	s show Iron
B. Descriptio	on of corner evidence fo	ound and/or method applied	in restoring or re-establish	ning corner:
			ection of 1/4 li	
1-4	Found 13" Iron		h of Road Center	
C. Description	of monument for corne	Corpore DV 4- D	shed to perpetuate locating	the position of the corner:
P.	n 8" Maple S 49 K in 10" Poplar 88 E 33.00'	5° E 65.51'; PK 1 c N 40° W 63.45';	Pole S 85° E 24. n 10" Elm N 50° I Concrete Monumer	78'; PK 5 86.86'; nt
Ta Ta	l" Iron Pipe le aple N 20° E 25 ag in 15" Maple 5° E 87.63'	oft in Corner as .25'; Tag in 6"   S 30° W 55.53';	found; Tag in Twi Mult. Maple S 75° Tag in 12" Maple	n 15" E 35.85';
GNED BY	Quall K	Nell		
RVEYOR'S MI	Gerald R. Mc CHIGAN REGISTRATION	TRAINAN //	DATE Septembe	r 9, 1977
THE PARTY NAMED IN	UNITED STATES AGE			(SEAL)
NED BY	CHIEF OF		DATEDATE	OF MICHIGANIAN CONTRACTOR OF MICHIGAN CONTRAC
PROVED AND	SIGNED BY	HIGAN REGISTERED LAND SURVEYOR	DATE *	ERALD R.
VEYOR'S MICH	IIGAN REGISTRATION	NO	Y MICHIGAN STATE HOARD OF RE	AND SURFILIE
No. ML M736		FORM APPROVED H	Y MICHIGAN STATE HOARD OF REALTH	GENTATION, JAN. 20, 1971 ED LAND SURVEYORS