LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Alpena (County)	Located	n:	Corner Code #				
1. Public Land Su	-	29N R 6E 29N R 6E		- 1			
2. Property Control in Section	_	R R		_			
3. Miscellaneous Property in Sec	ST ST	RR			Register	of Deeds Stamp	& File Num
4. Lot No	, Recorded Plat				A B C D F		
5. Private Claims	2 6 5	4 3	2 1				
state that under requirementioned in lines 1 are therefore as required in Department of the Inte Law and /or that the conformance with the	in a field survey on ements of P.A. 74, Michi and 2 above were in confo in the current manual of si rior, Bureau of Land Man priner points mentioned in rules of the Michigan Boo shed, re-established, mon	gan P.A. of 1970, the ormance with regulate ourvey instructions of pagement or by a dec on lines 3, 4 and 5 abourd of Land Surveyor	ne corner points ions and rules the United States cree of a Court of ove were in rs or by a Decree of		3 4 - 7 - 8 - 5 6 - 18 - 17 - 7 8 - 19 - 20 - 9 10 - 30 - 29 -	16151 21222	11 12 13 13 13 14 13 14 13 14 15 16 25
NOTE: Not more certificate.	than 2 corners, all in	the same town a	nd range, may be ı	ecorded on this	11	33 34 3	5 . 36
A. Description of o	original monument and	d accessories and	or subsequent res	oration:			
	oost. ech 7" N 13° E ech 5" S 11° W	12 links 18 links	I-7	GLO set post. Wit: Aspen Hemloo		20 links 35 links	
				Gary St. Charl shows an exis	es, RLS #27461, M ting concrete monu	arch 1981 surve ment.	ey sketch
B. Description of co	orner evidence found	and/or method ap	plied in restoring o	reestablishing	corner:		
	shed the South quarter e between corners I-7		14 midway I-7		cepted a 4" x 4" cor S. Scott and Assoc		nt presumed
C. Description of m	onument for corner ar	nd accessories es	tablished to perpet	uate locating the	e position of the c	orner:	
carsonite r Wit: Set Set Set	2" pipe with aluminum l marker post. nail in 10" Maple nail in 10" Maple nail in 10" Oak nail in 10" Maple	S 5° W 31.1 S 21° E 53.2 S 85° E 41.5 N 42° E 79.4	21' 53'	Wit: Set nail Set nail Set nail Set nail	concrete monumen in 8" Maple in 6" Maple in 6" twin Maple in 3" Spruce ump with scribes	S 15° E 20 N 87° E 19 N 18° W 17	.78' .33' .03' .92' .5'
Signed by	arl T. Ki	iskila	1+!	F MICHIGAN CARL IISKILA LAND RVEYOR No.	Average 6	-14-99	,

Signed by _

Surveyor's Michigan License No. 33981

CENSED LA FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

Date __

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	
Alpena Located In: Corr	ner Code #
1. Public Land Survey T_29N R_6E	K-7
T	16 Register of Deeds Stamp & File Num
4 Lot No. Recorded Plat	
4. Lot No, Recorded Plat 5. Private Claims	A B C D E F G H I J K L M 2 6 5 4 3 2 1
I, Carl T. Kiiskila, in a field survey on Aug. 12, 19 97 of state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner mentioned in lines 1 and 2 above were in conformance with regulations and therefore as required in the current manual of survey instructions of the Unit States Department of the Interior, Bureau of Land Management or by a decrease. Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 ab in conformance with the rules of the Michigan Board of Land Surveyors or becree of a Court of Law; established, re-established, monumented, recover found as expressed below:	o hereby points rules ed ee of a ove were y a
NOTE: Not more than 2 corners, all in the same town and range certificate.	, may be recorded on this
A. Description of original monument and accessories and/or subs	equent restoration:
K-7 GLO set section post – Lewis Clason D.S. 1839. Wit: Hard Maple 7" N 44° E 15 links Yellow Pine 20" S 34° W 63 links	16 - This position was not established during the original government survey.
B. Description of corner evidence found and/or method applied in	restoring or reestablishing corner:
K-7 Found and accepted a 1/2" pin in concrete believed to be set by R. S. Scott and Associates. This position has been used by area surveyors for surveys in the vicinity.	16 - Established the Southwest Corner of the Southeast Quarter of the Southeast Quarter of Section 11 per standard BLM instructions for subdivision of a section.
C. Description of monument for corner and accessories established	d to perpetuate locating the position of the corner:
K-7 Found concrete monument in road intersection. Wit: Set nail in 3" Russian Olive N 74° W 124.02' Set nail in 22" Red Pine S 46° W 65.89' Power pole N 50° E 45.83' Power pole S 61° E 113.10'	16 - Set 5/8" x 32" rerod with cap and set carsonite marker post. Wit: Set nail in 5" Maple S 47° W 21.01' Utility pole gate post S 73° W 41.63' Utility pole gate post N 77° W 40.92' Set nail in 5" Maple N 2° W 27.88' Carsonite post set South 15' ±
igned by Carl T Kiiskila	CARL KIISKILA LAND SURVEYOR Date Date
Surveyor's Michigan License No. 33981	33981 CAND LAND FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
	REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT., 1995

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Located In: Corner Code # Alpena 1. Public Land Survey 2. Property Controlling 14 T 29N R 6E 13 in Section T 29N R 6E 16 14 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Num ____, Recorded Plat 5. Private Claims I, Carl T. Kiiskila_, in a field survey on Nov. 03_, 19_97_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: 11 NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: 13 - This position was not established during the original 16 - This position was not established during the original government survey. government survey. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 13 - Established the Northeast Corner of the Southwest Quarter 16 - Established the Southeast Corner of the Southwest Quarter of the Southeast Quarter of Section 14 per standard BLM of the Southeast Quarter of Section 14 per standard BLM instructions for subdivision of a section. instructions for subdivision of a section. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 16 - Set 5/8" x 32" rerod with cap and set carsonite marker post. 13 - Set 5/8" x 32" rerod with cap and set carsonite marker post. N 6° W Wit: Power pole 34.47 Wit: Set nail in 4" and 8" twin Maple N 44° W 11.55' Guy pole S 51° W 22.92' Set nail in 3" Maple clump S 34° W 11.33' Set nail in 2" Oak S 45° E S 80° E 26.39 Set nail in 5" Maple 42.81' Set nail in 4" Oak N 33° E 79.19 S 34° E 60.83 Set nail in 3" and 6" twin Maple Centerline of east-west road North 7.5' ± 11.5' ± Centerline of north-south road East S 6°E Carsonite post set South 12.37 4" concrete monument (IISKILA LAND SURVEYOR Date CENSED LAND SUR Surveyor's Michigan License No. FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS.

ISED MAY