# SURVEY & REMONUMENTATION

APR 2 5 1995

### 1994 ALCONA COUNTY REMONUMENTATION CORNER

## COMMISSION

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

APPROVED LAND CORNER
P A 345 of 1990
ALCONA COUNTY -
BECORDED 3 10-9
County Rep & T
000.11)

For corners in	•
Alcona	Located In:
(County)	

Corner Code ##

T 25N R 6E Public Land Survey T \_\_\_\_\_ R \_\_\_\_ \_\_ R \_\_ T \_\_\_\_\_ R \_\_\_ **Property Controlling** 

\_\_ T \_\_\_\_ R \_\_ S \_\_\_\_ R \_\_ S \_\_\_\_ T \_\_\_ R \_\_\_\_ Miscellaneous Property in Sec.

MAR 10 10 21 AM '95 .

Davis a Die Thise
REGISTER OF DEEDS
ALCONA COLINY MICHIGAN Alcona County

Remonumentation


\_\_ , Recorded Plat \_

5. Private Claims \_

in Section

I Duane R. MacNeill, in a field survey on \_ <u>August 30, <sub>19</sub> 94</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

1844 - Cedar Post set by Government Surveyor 1984 - Surveyor, Robert Griffin sets concrete monument

Witnesses:

Beech 10 N25°E Beech 12 S25°W (No Witnesses provided)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Concrete monument appears to be at appropriate G.L.O. proportions between A-5 and C-5, thus it is being certified as being in correct location.

C. Description of manument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Remonumentation Crew found concrete monument with stamped brass cap. Left intact and provided witnesses.

#### Witnesses:

72.75 8" Twin W. Birch N35°W 8" W. Pine S40°W 66.40 200.10 8" W. Birch S10°E

No other witnesses available.

Surveyor's Michigan License No.

EACO LAND 19237

A CO LAND ST

Date December 28, 1994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975