1996 ALCONA COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74. Mich. P.A. 1970

APPROVED LAND CORNER
P A 345 of 1990
ALCONA COUNTY

County Rep. Di h. 6. 42 Filed for Record in ALCONA COUNTY MICHIGAN DORIS A GAUTHIER On 06-27-2000 At 09:17 am. LAND CORNER 9.00	For corners in	riling Requiren	nent of Act 74, Mich. P.	Date. 9-20 - 96
1. Public Land Survey T 26N R8E M-12 T 26N R9E A-12 T R Dn 06-27-2000 At 09:17 am. LAND CORNER 9.00	ALCONA	Located In:	Corner Code #	1) \(\sigma \) \(\sigma \) \(\sigma \)
2. Dramatic Controlling C. T. D.	1. Public Land Survey	T <u>26N</u> R <u>9E</u> T R	M-12 A-12	O Filed for Record in ALCONA COUNTY MICHIGAN DORIS A GAUTHIER On 06-27-2000 At 09:17 am.
in Section ST R Remonumentation				Alcona County Remonumentation
3. Miscellaneous S T F F Registration S T Registration Re		·		

		•
4.	. Lot No, Recorded Plat	
ō.	. Private Claims	<u> </u>

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:


1838: G.L.O. SURVEY by LEWIS CLASON - Set Post and Referenced

Hem.10 - S58W - 39 Beech 10 - N 35½W - 28

1994: Survey by Lewis and Lewis, Set ½" Iron Rod using 1/8 line information. Referenced: N62E-12" White Pine-53.71 feet S17E-12" White Pine-70.70 feet S12W-P. Pole- 170.49 feet N15W-P. Pole- 136.49 feet

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1996: Found 1/2" Iron Rod with cap #27452 in the North South road centerline.



JUN 2 9 2000

SECTION



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1996: Set a ½" Iron Rod with an Aluminum Cap stamped to identify the corner 6" below the road surface.

Referenced: N67E-15"Red Pine- 53.85 feet
S09E-12"White Pine-70.62 feet
N09W-Utility Pole-136.44 feet
S22W-Utility Pole-170.46 feet

NOTE - The purpose of this recording is to correct a Land Corner Recordation Certificate recorded in Liber 1, Page 171.

The Liber 1, Page 171 recorded Certificate incorrectly states that the subject corner is Corner M-12, T28N,R8E

/Corner A-12, T28N,R9E. The correct corner location is

Signed by Corner M-12, T26N, R8E/ Corner A-12, T26N, R9E. 6-22-2
--