REMONUMENTATION Jy. 2 JUN 1 4 1995 1994 Alcona County Remonumentation Corner LAND CORNER RECORDATION CERTIFICATE RECORDED Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Alcona (County) Located In: Corner Code # May 4 9 02 M '95 T 28NR 5E Public Land Survey Davis a Buther Remonument REGISTER OF DELDS COLIA _ B T APPROVED LAND CORNER Т R 2. Property Controlling P A 345 of 1990
ALCONA COUNTY
Register of Deeds Stamp & File-Number _T _ R in Section R Т S 3. Miscellaneous _ R_ Property in Section County Rep. __, Recorded Plat_ Lot No. 5. Private Claims _ , 19 I, David B. Guthrian a field survey on <u>June 6</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: 1840: G.L.O.

- Survey by Thos. Pattison Used 12" Sugar Maple for corner no references.
- Survey by W.S. Freer Set Pine stake 4" X 4" Referenced 1910: Fence Post - S77°W - 66 Links
- Survey by D.R. MacNeill and Assoc. 1987:
- 1993: Survey by D.R. MacNeill and Assoc. - Found 1" Pipe
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- Found P.K. Nail which is compatible with D.R. MacNeill and Assoc. 1994: surveys, did not find 1" pipe.
- NOTE The purpose of this recording is to correct the original Remonumentation Recording dated December 19, 1994. (Liber 1 Remon. Corners, Page 82.) The December 19, 1994 recording (Liber 1 of incorrectly listed the subject corner as B-1 on the Corner Grid Map. The subject corner is B-11.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- Replaced with a 5/8" Iron Rod with a 3" Aluminum Cap 1994: stamped Identify the Corner set in a Monument Box.

Referenced -

N50°W - 15" Basswood - 155.25 Feet S52°W - 14" W. Pine - 78.18 Feet S16°E - Anchor Pole - 23.53 Feet N25°E - Utility Pole - 31.00 Feet



Signed by	VaDB.	litter
g,		

May 1, 1995

Surveyor's Michigan License No.____

22435

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983