1994 Alcona C	ounty Remonumentati	on Corner	JUN I 4 199	15 3	10g. 2	
	LAND CORNE Filing Require	R RECORDATION CE	P.A. 1970		CORDED	
For corners in Alcona (County)	Located In:	Corner Code #	tion Page /	May 4	9 02 1	M '95
Public Land Survey	T <u>28NR 5E</u> T R T R	B-11 ———————————————————————————————————	Alcona County Remonumentation Liber / Page	ALCON [®]	A Designation of Delication	HIGAN
 Property Controlling in Section Miscellaneous Property in Section 	S T R S T R S T R S T R	<i>D</i>		APPROVE P A ALC er of Deeds	ONA COU	INTY
4. Lot No 5. Private Claims	, Recorded Plat			County F	Rep. <u>E</u> ,	H J K L
do hereby certify that under in lines 1 and 2 above were i manual of survey instructi Management or by a decree 5 above were in conforman	TIAn a field survey on	A. of 1970, the comer points rules therefore as required in the Interior, Bureau priner points mentioned in line pard of Professional Surveyo	mentioned the current of Land is 3, 4 and irs or by a red, found	3 4 7 8 5 6 18 17 7 7 8 19 20 9 10 30 29 1	-21 -2	10 — 11 — 12 — 13 — 15 — 14 — 13 — 12 — 24 — 1 — 12 — 27 — 26 — 25 — 25 — 25 — 25 — 25 — 25 — 25
NOTE: Not more than 4 on this certificate	corners, all in the same town and e.	l range, may bè recorded		11 12 13 13	33	34 35 36

- A. Description of original monument and accessories and/or subsequent restoration:
- 1840: Survey by Thos. Pattison - Used 12" Sugar Maple for corner G.L.O. no references.
- Survey by W.S. Freer Set Pine stake 4" X 4" Referenced 1910: Fence Post - S77°W - 66 Links
- Survey by D.R. MacNeill and Assoc. 1987:
- 1993: Survey by D.R. MacNeill and Assoc. - Found 1" Pipe
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- Found P.K. Nail which is compatible with D.R. MacNeill and Assoc. surveys, did not find 1" pipe.
- * NOTE The purpose of this recording is to correct the original Remonumentation Recording dated December 19, 1994. (Liber 1 Remon. Corners, Page 82.) The December 19, 1994 recording (Liber 1 of Remon. Corners, Page 82.) incorrectly listed the subject corner as B-1 on the Corner Grid Map. The subject corner is B-11.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 1994: Replaced with a 5/8" Iron Rod with a 3" Aluminum Cap Identify the Corner set in a Monument Box.

Referenced -

N50°W - 15" Basswood - 155.25 Feet S52°W - 14" W. Pine - 78.18 Feet S16°E - Anchor Pole - 23.53 Feet

N25°E - Utility Pole - 31.00 Feet

E OF MICHIC DAVID B. GUTHRIE UEVEY NO.

Signed by	VIDB.	litter
J.g., 3 J		

May 1, 1995

Surveyor's Michigan License No._

22435

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983