LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in field survey on August 16 19 78, established, re-established, monumented, re-monumented, recovered restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey of the formance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law: 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law: 1. W 1/16 corner on the north line of Sec. 25; not previously established. 2. E 1/16 corner on the north line of Sec. 25; not previously established. B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: 1. Set M.P.O.L. between the N.W. section corner and the Mc corner of Sec. 25. Old blazes E & W of corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.	1. PUBLIC LAND SURVEY. T. S., R. V. 2. PROPERTY CONTROLL 25 https://dx.com/property in section in	FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
3. MISCELLANEOUS PROPERTY IN SECTION, T	3. MISCELLANGOUS PROPERTY IN SECTION	1. PUBLIC LAND SURVEY	T S., R E.		
3. MISCELLANEOUS PROPERTY IN SECTION, T	3. MISCRLIANEOUS	2. PROPERTY CONTROLL- 25	, 44 N. 21 E. S., R. W.	1, 2	
A. LOT NO	4. LOT NO			ł	
I, David B. Babbitt do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1976, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in field survey on August 10 19.78, established, re-established, monumented, re-monumented, and successor and successor and successor and successor and successor and successor and successo	In David B. Babbitt do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on August 10 19 10, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on formance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law: 1. Survey on of original monument and accessories and/or subsequent restoration: 1. W 1/16 corner on the north line of Sec. 25; not previously established. 2. E 1/16 corner on the north line of Sec. 25; not previously established. B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: 1. Set M.P.O.L. between the M.W. section corner and the Mx corner of Sec. 25. 2. Set M.P.O.L. between the M.E. section corner and the Mx corner of Sec. 25. 3. Set M.P.O.L. between the M.E. section corner and the Mx corner of Sec. 25. 4. Set M.P.O.L. between the M.E. section corner and the Mx corner of Sec. 25. 4. Set M.P.O.L. between the M.E. section corner and the Mx corner of Sec. 25. 4. Set M.P.O.L. between the M.E. section corner and the Mx corner of Sec. 25. 4. Set M.P.O.L. between the M.E. section corner and the Mx corner of Sec. 25. 4. Set M.P.O.L. between the M.E. section corner and the Mx corner of Sec. 25. 4. Set M.P.O.L. between the M.E. section corner and the Mx corner of Sec. 25. 5. Set M.P.O.L. between the M.E. section corner and the Mx corner of Sec. 25. 6. Description of monument for corner and accessories established to perpetuate locating the position of the corner section and the Mx corner of				
the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in field survey on August 16 19.76, established, re-established, monumented, re-monumented, recovered as expressed below and in conformance with regulations and rules therefore as required in the current manus of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of court of law. Furthermore, that the corner points mentioned in lines 3,4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law: 1. W 1/16 corner on the north 11ne of Sec. 25; not previously established. 2. E 1/16 corner on the north 11ne of Sec. 25; not previously established. B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: 1. Set M.P.O.L. between the N.W. section corner and the Mc corner of Sec. 25. 2. Set M.P.O.L. between the N.E. section corner and the Mc corner of Sec. 25. 3. Old blazes E & W of corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner Both - 1" pipe, 4" aluminum cap 1. W s. maple - N639E - 49.95; 7" s. maple - Sh60E - 31.50'; 7" y. birch - S150E - 39" r. maple - N160W - 11.35'.	do hereby certify that under requirements of P.A.74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on August 10 19 T., established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3,4 and 5 above were, in a field survey on 19 —, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law: A. Description of original monument and accessories and/or subsequent restoration: 1, W 1/16 corner on the north line of Sec. 25; not previously established. 2, E 1/16 corner on the north line of Sec. 25; not previously established. B. Description of corner evidence found and/or method applied in restoting or re-establishing corner: 1, Set M.P.O.L. between the N.W. section corner and the Mc corner of Sec. 25. 2, Set M.P.O.L. between the N.W. section corner and the Mc corner of Sec. 25. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Both - 1" pipe, " aluminum cap 1, &" s. maple - M630E - 31.50'; 7" y. birch - S150E - 34. 9" r. maple = M630W - 11.35'. 2, 8" cedar - N860W - 11.55'; 6" cedar - S740W - 13.70'; 5" cedar - S420E - 4.70'; &" cedar - N850W - 11.55'; 6" cedar - S740W - 13.70'; 5" cedar - S420E - 4.70'; **SURVEYOR'S MICHIGAN REGISTRATION NO.	5. PRIVATE CLAIMS			
the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in field survey on Mugust 10 19 76, established, re-established, monumented, re-monumented, recovered restored as expressed below and in conformance with regulations and rules therefore as required in the current manus of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey of the month of the mo	the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on August 16 19 76, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the cutrent manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3,4 and 3 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law: A. Description of original monument and accessories and/or subsequent restoration: 1, W 1/16 corner on the north line of Sec. 25; not previously established. 2, E 1/16 corner on the north line of Sec. 25; not previously established. B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: 1, Set M.P.O.L. between the N.W. section corner and the Mk corner of Sec. 25. 2, Set M.P.O.L. between the N.E. section corner and the Mk corner of Sec. 25. 3, Set M.P.O.L. between the N.E. section corner and the Mk corner of Sec. 25. 4. Set M.P.O.L. between the N.E. section corner and the Mk corner of Sec. 25. 4. Section of monument for corner and accessories established to perpetuate locating the position of the corner. Both - 1" pipe, " aluminum cap 1, k" s. maple - N690E - 49.95; 7" s. maple - S460E - 31.50'; 7" y. birch - S190E - 34.99'; 7" s. maple - N690E - 11.55'; 6" cedar - 8740W - 13.70'; 5" cedar - S420E - 4.70'; 4" cedar - N450E - 4.40' SURVEYOR'S MICHIGAN REGISTRATION NO	Dewid R Rebbitt			
 W 1/16 corner on the north line of Sec. 25; not previously established. E 1/16 corner on the north line of Sec. 25; not previously established. B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Set M.P.O.L. between the N.W. section corner and the N% corner of Sec. 25. Set M.P.O.L. between the N.E. section corner and the N% corner of Sec. 25. Old blazes E & W of corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner both - 1" pipe, 4" aluminum cap	1. W 1/16 corner on the north line of Sec. 25; not previously established. 2. E 1/16 corner on the north line of Sec. 25; not previously established. B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: 1. Set M.P.O.L. between the N.W. section corner and the N% corner of Sec. 25. 2. Set M.P.O.L. between the N.E. section corner and the N% corner of Sec. 25. Old blazes E & W of corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Both - 1" pipe, 4" aluminum cap 1. 4" smaple - N630E - 49.95; 7" s. maple - S460E - 31.50'; 7" y. birch - S150E - 34. 9" r. maple - N180W - 11.35'; 2. 8" cedar - N860W - 11.55'; 6" cedar - S740W - 13.70'; 5" cedar - S420E - 4.70'; 4" cedar - N450E - 4.40' SIGNED BY	the corner points mentioned if ield survey on August 1 restored as expressed below a of survey instructions of the court of law. Furthermore 19, formance with the rules of the	in lines 1 and 2 above (ide 19 78, established and in conformance with regularity United States Department of that the corner points many found, recovered, restored,	ntified with circles on index d, re-established, monument ulations and rules therefore a the Interior, Bureau of Land mentioned in lines 3,4 and 5 established or re-established	code diagram – over) were, in a ed, re-monumented, recovered or as required in the current manual Management or by a decree of a above were, in a field survey on as expressed below and in con-
 1, Set M.P.O.L. between the N.W. section corner and the N.K. corner of Sec. 25. 2, Set M.P.O.L. between the N.E. section corner and the N.K. corner of Sec. 25. Old blazes E & W of corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corne Both - 1" pipe, 4" aluminum cap 1, 4" s. maple - N63°E - 49.95; 7" s. maple - S46°E - 31.50°; 7" y. birch - S15°E - 3 9" r. maple - N18°W - 11.35°. 	1. Set M.P.O.L. between the N.W. section corner and the Mc corner of Sec. 25. 2. Set M.P.O.L. between the N.E. section corner and the Mc corner of Sec. 25. Old blazes E & W of corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Both - 1" pipe, 4" aluminum cap 1. 4" s. maple - N630E - 49.95; 7" s. maple - S460E - 31.50'; 7" y. birch - S150E - 34. 9" r. maple - N180W - 11.35'. 2. 8" cedar - N860W - 11.55'; 6" cedar - S740W - 13.70'; 5" cedar - S420E - 4.70'; 4" cedar - N450E - 4.40' SIGNED BY	A. Description of original mor	the north line of Sec	25; not previously	established. established.
 Set M.P.O.L. between the N.W. section corner and the N.K. corner of Sec. 25. Set M.P.O.L. between the N.E. section corner and the N.K. corner of Sec. 25. Old blazes E & W of corner. Description of monument for corner and accessories established to perpetuate locating the position of the corner both - 1" pipe, 4" aluminum cap 4" s. maple - N63°E - 49.95; 7" s. maple - S46°E - 31.50°; 7" y. birch - S15°E - 3 9" r. maple - N18°W - 11.35°. 	1, Set M.P.O.L. between the N.W. section corner and the N% corner of Sec. 25. 2, Set M.P.O.L. between the N.E. section corner and the N% corner of Sec. 25. Old blazes E & W of corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Both - 1" pipe, 4" aluminum cap 1, 4" s. maple - N630E - 49.95; 7" s. maple - S460E - 31.50'; 7" y. birch - S150E - 34. 9" r. maple - N180W - 11.35'. 2, 8" cedar - N860W - 11.55'; 6" cedar - S740W - 13.70'; 5" cedar - S420E - 4.70'; 4" cedar - N450E - 4.40' SIGNED BY				
 1, Set M.P.O.L. between the N.W. section corner and the N.K. corner of Sec. 25. 2, Set M.P.O.L. between the N.E. section corner and the N.K. corner of Sec. 25. Old blazes E & W of corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corne Both - 1" pipe, 4" aluminum cap 1, 4" s. maple - N63°E - 49.95; 7" s. maple - S46°E - 31.50°; 7" y. birch - S15°E - 3 9" r. maple - N18°W - 11.35°. 	1. Set M.P.O.L. between the N.W. section corner and the Mc corner of Sec. 25. 2. Set M.P.O.L. between the N.E. section corner and the Mc corner of Sec. 25. Old blazes E & W of corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Both - 1" pipe, 4" aluminum cap 1. 4" s. maple - N630E - 49.95; 7" s. maple - S460E - 31.50'; 7" y. birch - S150E - 34. 9" r. maple - N180W - 11.35'. 2. 8" cedar - N860W - 11.55'; 6" cedar - S740W - 13.70'; 5" cedar - S420E - 4.70'; 4" cedar - N450E - 4.40' SIGNED BY			•	
 Set M.P.O.L. between the N.W. section corner and the N.K. corner of Sec. 25. Set M.P.O.L. between the N.E. section corner and the N.K. corner of Sec. 25. Old blazes E & W of corner. Description of monument for corner and accessories established to perpetuate locating the position of the corner both - 1" pipe, 4" aluminum cap 4" s. maple - N63°E - 49.95; 7" s. maple - S46°E - 31.50°; 7" y. birch - S15°E - 3 9" r. maple - N18°W - 11.35°. 	1, Set M.P.O.L. between the N.W. section corner and the N% corner of Sec. 25. 2, Set M.P.O.L. between the N.E. section corner and the N% corner of Sec. 25. Old blazes E & W of corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Both - 1" pipe, 4" aluminum cap 1, 4" s. maple - N630E - 49.95; 7" s. maple - S460E - 31.50'; 7" y. birch - S150E - 34. 9" r. maple - N180W - 11.35'. 2, 8" cedar - N860W - 11.55'; 6" cedar - S740W - 13.70'; 5" cedar - S420E - 4.70'; 4" cedar - N450E - 4.40' SIGNED BY				
 Set M.P.O.L. between the N.W. section corner and the N% corner of Sec. 25. Set M.P.O.L. between the N.E. section corner and the N% corner of Sec. 25. Old blazes E & W of corner. Description of monument for corner and accessories established to perpetuate locating the position of the corner Both - 1" pipe, 4" aluminum cap 4" s. maple - N63°E - 49.95; 7" s. maple - S46°E - 31.50°; 7" y. birch - S15°E - 3 9" r. maple - N18°W - 11.35°. 	1, Set M.P.O.L. between the N.W. section corner and the N. corner of Sec. 25. 2, Set M.P.O.L. between the N.E. section corner and the N. corner of Sec. 25. Old blazes E & W of corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Both - 1" pipe, 4" aluminum cap 1, 4" s. maple - N630E - 49.95; 7" s. maple - S460E - 31.50'; 7" y. birch - S150E - 34. 9" r. maple - N180W - 11.35'. 2, 8" cedar - N860W - 11.55'; 6" cedar - S740W - 13.70'; 5" cedar - S420E - 4.70'; 4" cedar - N450E - 4.40' SIGNED BY				
1, 4" s. maple = N63°E = 49.95; 7" s. maple = S46°E = 31.70°; 7" y. offen = S17 E = 3 9" r. maple = N18°W = 11.35°.	1, 4" s. maple - N630E - 49.95; 7" s. maple - S460E - 31.50"; 7" y. 517ch - 517 E - 54. 9" r. maple - N180W - 11.35". 2, 8" cedar - N860W - 11.55"; 6" cedar - S740W - 13.70"; 5" cedar - S420E - 4.70"; 4" cedar - N450E - 4.40" SIGNED BY	1, Set M.P.O.L. between 2, Set M.P.O.L. between	een the N.W. section een the N.E. section	corner and the No cor	ner of Sec. 25.
9" r. maple - N180W - 11.35'. 2, 8" cedar - N860W - 11.55'; 6" cedar - S740W - 13.70'; 5" cedar - S420E - 4.70'; 4" cedar - N450E - 4.40'	2, 8" cedar - N86°W - 11.55'; 6" cedar - S74°W - 13.70'; 5" cedar - S42°E - 4.70'; 4" cedar - N45°E - 4.40' SIGNED BY	C. Description of monument Both - 1" pipe, 4" alu 1. 4" s. maple - N63	for corner and accessories uminum cap DE = 49.95; 7" s. map	established to perpetuate locale - S46°E - 31.50°;	rating the position of the corner: 7" y. birch - S15 ⁰ E - 34.00
2, 8" cedar - N86°W - 11.55'; 6" cedar - S74°W - 13.70'; 5" cedar - S42°E - 4.70'; 4" cedar - N45°E - 4.40'	SIGNED BY DATE SURVEYOR'S MICHIGAN REGISTRATION NO (SEAL)	9" r. maple - N189	W = 11.35'.		_
	SURVEYOR'S MICHIGAN REGISTRATION NO (SEAL)	2, 8" cedar - N86°W - 4" cedar - N45°E	- 11.55'; 6" cedar - - 4.40'	874°W - 13.70°; 5° ce	dar - S42°E - 4.70';
	SURVEYOR'S MICHIGAN REGISTRATION NO (SEAL)				
SIGNED BY DATE		SIGNED BY		DATE	
SURVEYOR'S MICHIGAN REGISTRATION NO (SEAL)	FOR STATE AND UNITED STATES AGENCIES:	SURVEYOR'S MICHIGAN RE	GISTRATION NO.		(SEAL)
FOR STATE AND UNITED STATES AGENCIES:		FOR STATE AND UNITED S	TATES AGENCIES:		
we a dispersi	SIGNED BY DATE	SIGNED BY		DATE	
	CYTET OF STRVEY PARTY 9-7-78		2-1-01	Ballitt DATE	9-7-78
CYTET OF SARVEY PARTY	APPROVED AND SIGNED BY MICHIGAN REGISTERED LAND SURVEYOR (SEAL)	APPROVED AND SIGNED BY	MICHIGAN REGISTERED I	LAND SURVEYOR	
APPROVED AND SIGNED BY DATE 9-7-78		SURVEYOR'S MICHIGAN RE	GISTRATION NO. 215	558	

Form No. ML M736

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28 171 DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERS, LAND 1717