Daniel Crotti	by Alger County y Remonumentation p Under Act 345 of On19_44
21	1.0 w Culson

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

4-248

Chairman For corners in	Filing Require	ement of Act 74, Mich. P.A.	1970	- 270	
Alger	Located In:	Corner Code ##			
in Section S 3. Miscellaneous S	T 45N R 21W T R R R R R R R R R R R R R R R R R R	<u>C1</u>	Recorded July 15, 1994 at 8:00 o'clock A. M., and Recorded in Liber 4 of Cor. Rec. on Page 248 Alger County Register of Deeds Register of Deeds Stamp & File Number		
4. Lot No, Recorde	d Plat		АВСО) EFG. HIJK L W	
in a fi do hereby certify that under requirement in lines 1 and 2 above were in confort current manual of survey instructions of Management or by a decree of a Court of above were in conformance with the ru Court of Law; established, re-estable expressed below: NOTE: Not more than 4 corners, on this certificate. A. Description of original monument C1: P.L.S., John Burt, DS, 1841. St. Paul and Sault Ste. Marie Rail of way. Edwin Swan, R.L.S., 1948 Corner, 14* below road surface, at feet.	ield survey onSeptents of P.A. 74, Michigan P.A. mance with regulations and the United States Depart of Law and/or that the corneles of the Michigan Board of Lished, monumented, remail in the same town are ent and accessories and Sugar 12, Cor of Secs, road Right of Way Map, Cand 1949, Alignment note	of 1976, the corner points mentione id rules therefore as required in the timent of the Interior, Bureau of Lander points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of monumented, recovered, found and range, may be recorded d/or subsequent restoration: 31 & 32. Sugar 18, N.40 W., 3: October 27, 1902. Corner noted es for Eben-Trenary road, Alger	2. Sugar 18, S.65 E. 1104 feet East of ce County Road Commissi	enterline of railroad right ion. Standard Alger County	
B. Description of corner evidence C1: At the centerline of the inte identify from reference objects, o remains is base plate. Reaction o reaction on locater consistently g monument, and the roadbed has been shown on alignment plans. Install position of the original corner.	ersection of Tunteri and objects destroyed. Removen on locator was weak and co got better the deeper the or raised over the course	Eben-Trenary roads found 1/2" ved rebar and with locator dete centralized. Dug small hole the probe. It was determined that of the years. Location indexes	rebar flush with asph rmined that A.C. Star rough asphalt to a de t all that remains is s well with A.C. Road	ndard was deep or all that epth of 24° and tone s the baseplate of A.C. d Commission location as	
		,			
C. Description of monument for CC: Installed 5/8" x 18" rebar w/Alum. cap stamped to I.D. corner position, grouted in concrete. Es reference points and reference tre w/BT signs, blazed, scribed and pa Set PK nails for measuring w/brass washers in the following reference trees. Anchor Pole, N.52W., 42.44 "BT". Power Pole, N.46 E., 48.34 "BT". Gas Line Marker Post, S.68 84.93 feet. Maple 18", S.77 W. 5 feet "BT".	3 1/4' st. ses sinted. s I.D. feet, feet, E.,	nus Date	! June	1994	
Surveyor's Michigan License No		FO	RM APPROVED BY MICHIGAN STAT	re Board of Land Surveyors, Jan. 28, 1971 Revised May 14, 1975 Revised Jan., 1983	