Approved by Alg	or County
Land Survey Florid	วิทยาวอกรณ <b>์เอก</b>
Pear Grown Under	マウがななん
P.A. of 1935 On 3	-2419 <u>97</u>
1100	

Chairman LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

5-18

_	ALGER "	Located In:	Corner Code #	enti mila	
	(County)			FILED TIME	
1.	Public Land Survey	T 45N R 21H		TIVE	
		T <u>46</u> NR 21V T R		MAR 3 1 1997	
2.	Property Controlling	T R ST R	1	DONALD W. KINNUNEN REGISTER OF DEEDS	
	in Section	ST R		ALGER COUNTY, MI	
3.	Miscellaneous	\$ T R		Devision of Devision of Black and a	
	Property in Section	ST R		Register of Deeds Stamp & File Number	
1	f ot No	, Recorded Plat		T. 46N. R.ZIW. G13	
		, recorded reat		A B C D E F G H I J K L M	
٠.	Tittate Olaitio			2 - 6 5 3 2 1	
	•			3	
	Robert L. Jamros	c	September 18, 1996	4 7 - 8 - 9 - 10 - 11 - 12 -	
i,		, in a field survey on	, 19		
do	do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned				
	in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land				
	Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and  8 19 20 21 21 22 23 24				
	5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a				
	cree of a Court of Law; expressed below:	stablished, re-established, monume	nted, re-monumented, recovered, f	ound 10 30 29 28 27 26 25	
	•		d	11-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1	
M	on this certificate	comers, all in the same town an	d range, may be recorded	12 31 32 33 34 35 36	
				13	
Ą	Description of origin	al monument and accessories	and/or subsequent restoration	: 4 lks. * Sugar 9, N.60 W., 40 lks. ***** Z.B.	
				** Geo. L. Depew, CS, 1917. * Placed stand. iron	

Description of original monument and accessories and/or subsequent restoration:
G1: PLS - John Burt, DS, 1841, Set post cor. of Secs. 33 & 34 \* Sugar 14, N.12 E., 14 lks. \* Sugar 9, N.60 W., 40 lks. \*\*\*\*\* Z.B.

Searls, DS, 1850. \* Post, Sugar 26, S. 56 W., 21 lks. \* Sugar 8, S.46 E. 34 lks. \*\*\*\*\* Geo. L. Depew, CS, 1917. \* Placed stand. iron cor. \*\*\*\*\*\* Cor. shown on MDSH State Trunkline Rd. Plans at Alger Co. Road Comm. \* Surveyed and mapped by G.L. Depew, CS, 1919. \* No wit. or mon. material shown. \*\*\*\*\* M.S.H.D., 1959 Proj., Munising-Chatham Rd. \* Cor. position shown at hwy. sta. 536+91.38. \* Iron mon. in Mon. box on survey CL. \*\*\*\*\* Herbert L. Fluharty, RLS, 1975. \* Fd. 3/4\* Iron bar at CL inter. M-94 & M-67 in Mon. box. \* T.P., N.70 W., 71.08' \* P.P., S.58 W., 67.07' \* P.P., S.63 E., 96.19' \* Recorded in L.1, P.76, Alger Co. Records. \*\*\*\*\* Robert L. Jamros, RLS, 1990. \* Alger Co. Rd. Comm. Proj. for the rehabilitation of Tunteri Rd. Exist. 3/4\* Iron bar recovered. \* ACRC Files \*\*\*\*\* Robert F. Cambensy, R.L.S., 1993. \* Fd. 3/4\* iron pin w/ 1 1/4\* sq. top in mon. box, CL of inter. of Hwy. M-94 & Hwy. M-67. \* Replaced fd. 3/4\* iron pin w/ 5/8\* x 18\* Rebar w/ 3 1/4\* Alum. cap, stamped to identify cor. position.\* S.E. cor. of conc. culv. hdwl, \$ .31 E., 69.26'\* S.W. cor. of conc. culv. hdwl, \* P.Pole, N.72 E., 295.53'to nail. \* P.Pole, N.27 W., 132.11'to nail.\* L.4, P.210, A.C. Records.

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
G1: Found 3 1/4' Bernsten Aluminum cap on 5/8' Rebar, stamped to identify corner position in Monument box at centerline of intersections, M-94 and M-67. \* Measurements to corners West and East are 2638.71 and 2636.59, respectively. \* Monument in box at existing corner position is accepted as the best available evidence of the position of the original corner.

## SURVEY & REMONUMENTATION

AUG 1 5 1997

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

61: Accepted monument at existing corner position as found. Verified existing witness of the 1993 report. \* Southeast corner of concrete culvert headwall, S.31 E., 69.26 feet. \* Southwest corner of concrete culvert headwall, S.26 W., 66.86 feet. \* P. Pole, N.72 E., 295.53 feet, existing nail and washer. \* All bearings are magnetic.

Signed by taket &

Surveyor's Michigan License No. /

25849

FODERT L.

ZAMMEDS

PROFESSIONAL

SUPERVOR

ate 25 March, 1997

rm approved by Michigan State Board of Professional Surveyors, Jan. 28, 1971 Revised May 14, 1975 Revised Jan., 1983