LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

	FOR CORNERS OF-:	LOCATED IN -:	CORNER CODE NUMBER	
	1. PUBLIC LAND SURVEY	T. 45 S., R. 22 E.	E-6, F-5	
	2. PROPERTY CONTROLL- 1	6 ,T. 45 N. R. 22 W.	1	•
	3. MISCELLANEOUS PROPERTY IN SECTION	,T		
	4. LOT NO, RECORDED PLAT			
	5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
	the corner points mentioned field survey on August 2 restored as expressed below of survey instructions of the court of law. Furthermore 19	in lines 1 and 2 above (ide 5 1980, established and in conformance with regular United States Department of the corner points of found, recovered, restored,	entified with circles on indexed, re-established, monumente gulations and rules therefore a f the Interior, Bureau of Land mentioned in lines 3,4 and 5 established or re-established	P.A. 74, Michigan P.A. of 1970, code diagram — over) were, in a ed, re-monumented, recovered or a required in the current manual Management or by a decree of a above were, in a field survey on as expressed below and in contra or, by a Decree of a Court of
E- 6	A. Description of original monument and accessories and/or subsequent restoration: West & corner - Section 16; Wood Post, Spruce 5 - M40 W - 12 lks.; Cedar 12 - S65 E - 10 lk			
F-5	k Corner between Sec. 9 and 16; Wood Post, B. Ash 10 - N20°E - 32 lks.; Y. Birch 10 - S58°W - 11 lks.			
1	West 1/16 between Sec. 9 and 16; not previously established.			
	B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Set M.P.O.L. between the N.W. and S.W. section corners of Sec. 16. No sign of O.B.T.'s. Found old square stake - not of record but it fits surrounding corner locations very well. No sign of O.B.T.'s. Replaced stake with D.N.R. monument.			
1	Set M.P.O.L. between th	•		er of Section 16
	C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 1" pipe, 4" aluminum cap. 7" Cedar - N65°W - 7.2°; 6" Cedar - S32°W - 3.05°; 8" Cedar - N79°E - 11.75°; 10" Cedar - S53°E - 19.0°.			
ALL E-6	1" pipe, 4" aluminum ca 7" Cedar - N65°W - 7.2°		3.05'; 8" Cedar - N79	
	1" pipe, 4" aluminum ce 7" Cedar - N65°W - 7.2° S53°E - 19.0°.	np. 1; 6" Cedar - S32°W -	•	
	1" pipe, 4" aluminum ca 7" Cedar - N65°W - 7.2° S53°E - 19.0°.	; 6" Cedar - S32°W - ; 4" B. Ash - S75°E	- 9.8°; 8° W. Spruce -	PE - 11.75'; 10" Cedar - N49°E - 19.9'; 6" Cedar -
F-5	1" pipe, 4" aluminum ca 7" Cedar - N65°W - 7.2" S53°E - 19.0". 4" Cedar - S51°W - 8.7" N12°W - 19.8". 28" H. Maple - N50°E - 12" H. Maple - S20°E -	1; 6" Cedar - S32°W - 2; 4" B. Ash - S75°E 10.4°; 6" H. Maple - 21.7°.	- 9.8°; 8° W. Spruce -	TE - 11.75'; 10" Cedar - N49°E - 19.9'; 6" Cedar - Maple - S38°W - 10.2';
F-5	1" pipe, 4" aluminum ca 7" Cedar - N65°W - 7.2" S53°E - 19.0". 4" Cedar - S51°W - 8.7" N12°W - 19.8". 28" H. Maple - N50°E - 12" H. Maple - S20°E -	1; 6" Cedar - S32°W - 2; 4" B. Ash - S75°E 10.4"; 6" H. Maple - 21.7".	- 9.8'; 8" W. Spruce - N46°W - 22.0'; 15" H.	TE - 11.75'; 10" Cedar - N49°E - 19.9'; 6" Cedar - Maple - S38°W - 10.2';
F-5	1" pipe, 4" aluminum ca 7" Cedar - N65°W - 7.2" S53°E - 19.0". 4" Cedar - S51°W - 8.7" N12°W - 19.8". 28" H. Maple - N50°E - 12" H. Maple - S20°E -	2. 6" Cedar - S32°W - 2; 4" B. Ash - S75°E 10.4°; 6" H. Maple - 21.7°.	- 9.8'; 8" W. Spruce - N46°W - 22.0'; 15" H.	PE - 11.75'; 10" Cedar - N49°E - 19.9'; 6" Cedar - Maple - S38°W - 10.2';
F-5	1" pipe, 4" aluminum ca 7" Cedar - N65°W - 7.2° S53°E - 19.0°. 4" Cedar - S51°W - 8.7° N12°W - 19.8°. 28" H. Maple - N50°E - 12" H. Maple - S20°E - SIGNED BY	2. 6" Cedar - S32°W - 2; 4" B. Ash - S75°E 10.4°; 6" H. Maple - 21.7°.	- 9.8°; 8° W. Spruce - N46°W - 22.0°; 15° H DATE	PE - 11.75'; 10" Cedar - N49°E - 19.9'; 6" Cedar - Maple - S38°W - 10.2';

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971 DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

Form No. MLM735 DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.