Approved to Alga, Go Land Survey Remonunch, Un Peer Group Under Adi \$45 of P.A. of 1930 On 12-(2-1995

JAN 2 3 1996

Serell Walson	
Chairman	

For corners in

as expressed below:

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION 4-329

(County)		Located in:	Comer Code #			
1.	Public Land Survey	T 46N R18W T 46N R17W	M5 (A5)			
2.	Property Controlling	T R T R S T R				

REC'D and FILED

SEC 20 1395 DONALD W KINNING Y County Clerk

e Number

3. Miscellaneous Property in Section	. Miscellaneous S T R			egister of Deeds Stamp & Fi						
4. Lot No.				 ,	A B	С	D	E !	F G	<u>i 1</u>
5. Private Claims	 					\perp	-5	<u> </u>		a
				3	\vdash	+	+-	$\left\{ -\right\}$		-
Onhart I Tampa		Tuna A7 100F		4	<u></u>	+	.8		-	10
Robert L. Jamros				5	┝╼┿╌	-+	+	├─┤		
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned				6	18-	-	17	16	-	15—15
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land				7		-	-	\vdash \dashv		\dashv
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and				8	—19 -	+	20	21	1-	-22
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a						1	1 '	. !		- 1

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

A. Description of original monument and accessories and/or subsequent restoration:

Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found

M5: PLS-William A. Burt, DS, 1841, Set post corner of sections 12 & 13 - Sugar 24", S.71 E., 25 links, Sugar 24", N.64 W., 52 links. Alger County Road Commission, George L. Depew, County Surveyor, 1917, placed iron corner at section corner. No references given. CCI Forestry Division, Iron pipe shown on map of section twelve, No references given. Author of map unknown.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M5: Found remains of Alger County standard monument, two inch galvinized iron pipe with brass cap missing, in upright position. Corner position lies on centerline of road to south and east. A Search was made at GLO bearing tree positions, evidence is lost. Corner position is accepted as the best available evidence of the position of the original corner.

C. Description of monument for comer and accessories established to perpetuate locating the position of the corner:

M5: Installed 5/8" x 18" rebar w/ Berntsen Cap no. RBD5325 stamped to identify corner position, in centerline of existing two inch pipe. Established the following reference trees w/ BI signs, blazed, scribed and painted. Set PK nails for measure w/ Alum. I.D. washers in the following reference trees. Maple 5", S.42 W., 29.73 feet, "S13 BI", P.Pole, N.47 W., 35.21 feet, "Scribed BT & base of pole ", SW Cor. Hse. Conc. 8lk. Foundation, N.44 E., 87.50 feet, Maple 5", S.39 E., 129.83 feet, "S18 BI". All bearings are magnetic.

OF MIC

ROBERT L JAMR**OS**

Signed by Surveyor's Michigan License No.

m ber Pates:://key FORM APPROVED BY MICHIGUESTATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 25849 SURVINIONE LAND SURVINIONE

EVISED MAY 14, 1975 REVISED JAN., 1983