## SURVEY & REMONUMENTATION

Approved by Alger County Land Survey Remonumentation Peer Group Under Apt 345 of

JUL 3 0 1996

P.A. of 1990 On <u>5/8</u> 19 <i>9</i> De Villa a a le Villa		MMISSION RECORDATION CERTIF	4-387
Chairman For corners in Alger (County)		nent of Act 74, Mich. P.A. Corner Code #	IOAIL
Public Land Survey	T R T R T R T R	N8 A-8	JUN 27 1996  DONALD W. KINNUNEN REGISTER OF DEEDS
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Section</li> </ol>	S T R S T R S T R S T R		ALGER COUNTY, MI  Register of Deeds Stamp & File Number
4. Lot No, Rec 5. Private Claims	corded Plat		A B C D E F G H 1 J K L M 2 6 5 4 3 2 1 1 1 1 1 1 2 1 1 1 1 1 2 1 1 1 1 1
do hereby certify that under requi in lines 1 and 2 above were in cor manual of survey instructions Management or by a decree of a 5 above were in conformance w	rements of P.A. 74, Michigan P.A. of the United States Departme Court of Law and/or that the corrith the rules of the Michigan Boaished, re-established, monumented	of 1970, the comer points mention es therefore as required in the cur int of the Interior, Bureau of L her points mentioned in lines 3, 4 and of Professional Surveyors or l	oned 6 18 17 16 15 14 13 13 14 13 15 14 13 15 14 13 15 14 15 15 14 15 15 14 15 15 15 15 15 15 15 15 15 15 15 15 15
NOTE: Not more than 4 come on this certificate.	•	•	12 31 32 33 34 35 36
A Description of original m	onument and accessories and	d/or subsequent restoration:	

M8: PLS-William A. Burt, D5, 1841, Set qr. section post - Sugar 8\*, S.49 E., 42 links, Sugar 16\*, N.20 W., 17 links. No subsequent restoration.\*\*\*\*\* Alger County Road Commission, 1986-1989, Robert L. Jamros,PS, established corner position at single proportionate measurement between existing corners North and South for road alignment purposes prior to the reconstruction and paving of Percy Road.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M8: Found 1/2' Rebar with I.D. cap no. 25849, 1.8 feet East of the centerline of Percy Road, at surface of road. Corner position verified as being established on line and at single proportionate distance between BT Section corner of Sections 13, 24, 18, and 19, T.46N., R.17-18W., and BT Section corner of Sections 25, 36, 30, and 31, T.46N., R.17-18W. Corner position lies in an improved area along Percy Road and all evidence of original BT's has been destroyed. Corner position lines well with dim fence west and northerly edge of open field. Corner position is accepted as a careful and faithful reestablishment of the position of the original corner.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M8: Set in place of exist. 1/2" rebar a 5/8"x 18" rebar with Berntsen 3 1/4" aluminum cap no. RBD5325, stamped to identify corner position, grouted in place with concrete. Established the following reference trees.\*\* Maple 18', N.66 W., 47.40 feet, PK W/ aluminum I.D. washer.\*\* Maple 18", S.28 W., 111.10 feet, PK w/ aluminum I.D. washer.\*\* Maple 10", N.47 E., 50.77 feet, PK w/ aluminum I.D. washer, Blazed, Painted, Scribed "1/4S BT" and BT signs.\*\* Maple 12", S.38 E., 51.29 feet, PK w/ aluminum I.D. washer, Blazed, Painted, Scribed "1/4S BT" and BT signs. All bearings are magnetic.

Signed by\_

Surveyor's Mighigan License No.

12566 N STATE BOARD OF PROPE FORM APPROVED BY MICHIG

ROBERT L. JAMEOS PROFESSIONAL SURVEYOR No.

> IONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983