SURVEY & REMONUMENTATION

Approved by Alger County
Land Survey Remonumentation
Peer Group Under Act 245 of
P.A. of 1990 On 1990

FEB 2 3 1999

Signed by

	Chairman		FER RECORDATION CERTIFICATION OF ACT 14. Mich. P.A. 19	
For co	mers in		O O . J . #	سري د سر څ د مهست
	Alger (County)	Located In:	Comer Code #	TIME 10:00 AM.
1. Put	olic Land Survey	T <u>46N R17W</u> T <u>46N R18W</u> T <u>45N R17W</u>	M 13 A 1	JAN 8 1999 DONALD W. KINNUNEN
in S 3. Mis	perty Controlling Section cellaneous perty in Sec.	T <u>45N</u> R <u>18W</u> S T R S T R S T R S T R	<u>M 1</u>	REGISTER OF DEEDS ALGER COUNTY, MI
•	•			Register of Deeds Stamp & File Numb
4. Lot 5. Priv	vate Claims	orded Plat		A B C D E F G H I J K I
				2 6 - 5 - 4 3 - 2 - 1
				3 - 10 - 11 - 1
I, Robert L. Jamros, in a field survey on November 25, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in				
		he Michigan Board of Land Surve iumented, recovered, found as exp	yors or by a Decree of a Court of Law, ressed below:	B 19 20 21 22 23 2
NOTE	: Not more than 2 co	omers, all in the same town an	nd range, may be recorded	10 30 29 28 27 26 2
	on this certificate.			11
Δ D	escription of original	monument and accessories	and/or subsequent restoration:	12 31 32 33 34 35 3
A13: P.L.S William A. Burt, DS, 1841. Intersect West township boundary at post, corner of Townships 45 and 46 North, between Ranges 17 and 18 West (post set as temporary in T.45N., R.17W.) * Hemlock 16, N.63°E., 29 links. * Hemlock 20, N.59°W., 54 links. ***** John Burt, DS, 1841. West on the South side of Section 36, T.46N., R.18W., * Hemlock 16, N.63°E., 29 links. * Hemlock 20", N.59°W., 54 links. ***** The following are unrecorded reports from USDA Forest Service Records. ***** L. Lammi, USDA, Forest Service, 1974. Found wood post blazed on 2 sides. 76.38 ch. was written on post with section line brushed North of corner. ***** Glenn A. Bergey, RLS, 1974. * Found wood post at edge of clearing, could not verify. ***** No other record of restoration.				
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:				
A13: Located corner position by standard field survey and double proportionate measurement to section corners, 1 mile North 1 mile East, 3 miles South and 4 miles West. Found wooden post of 1974 reports at edge of clearing 60 feet more or less East of corner position, down and decayed. A search was made for original evidence, none remains. Area around corner position appears to be graded, with evidence of dim track roads, dump piles and timber cutting. Monumented corner position as established and made new reference trees. Corner position is accepted as a careful and faithful reestablishment of the position of the original corner.				
c.	Description of moni	ument for corner and access	ories established to perpetuate loca	ting the position of the corner:
A13:	A13: Set Berntsen aluminum monument no. AINB30 with 3 1/4" aluminum cap, stamped to identify corner position. Established new reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following. * White Spruce 7", S.48°W., 17.75 feet, "S1 BT"; * Black Spruce 6", N.28°W., 15.09 feet, "S36 BT"; * White Pine 4", N42°E., 17.01 feet, "S31 BT"; * Maple 4", S.53°E., 19.65 feet, "S6 BT". * Survey marker sign on 6 foot steel post, S.24°W., 1.0 feet. * All bearings are magnetic.			
	0			

Surveyor's Michigan Vicense No 25849 ROBERT L. **JAMROS** PROFESSIONAL SURVEYOR No. 25849 POFESSIONAL

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,197 REVISED JAN, 198 REVISED OCT, 199

Date December 16, 1998