## SURVEY & REMONUMENTATION

Approved by Alger County
Land Survey Remonumentation

FEB 2 3 1999

JAMROS PROFESSIONAL SURVEYOR

No. 25849 POFESCIONAL

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970  For corners in  Alger	Peer Group Under Apt 345 of P.A. of 1990, On	ξ	SECTION					وسسيد	-7*	20	
Alger Located In: Corner Code #    Alger   Located In: Corner Code #   County	Musavis RLS						0	5 7	-10	. 0	
Alger Located In: Corner Code #    County   County   County		Filing Requ	irement of Act 74, Mich. P.	A. 1970							
1. Public Land Survey  T46N R17W TR											
1. Public Land Survey  T46N R17W  TR  TR  TR  TR  TR  D11  TR  TR  DONALD W. KINNUNEN REGISTER OF DEEDS ALGER COUNTY, MI  Register of Deeds Stamp & File Number  4. Lot No.  Recorded Plat  5. Private Claims  In a field survey on December 2 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 1 and 2 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law and for that the corner points mentioned in lines 3 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, monumented, recovered, found as expressed below:  NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  D11: P.L.S William Iwes, DS, 1850. * Set quarter section post. * Tamarack 8, S.70*E., 18 links. * Tamarack 8, N.57*W., 22 links. ************************************		Located in:	Corner Code #			5 <b>=</b>		 ~/2	A-1	n.	
TR R DONALD W. KINNUNEN REGISTER OF DEEDS  2. Property Controlling S T R R R REGISTER OF DEEDS  3. Miscellaneous S T R R R REGISTER OF DEEDS  4. Lot No. Recorded Plat  5. Private Claims  In a field survey on December 2 19 98 do hereby state that under requirements of PA. 74, Michigan PA. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a Court of Law and/ or that the corner points mentioned in lines 1 or survey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a Court of Law and/ or that the corner points mentioned in lines 3 days and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below.  NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  D11: P.L.S William Ives, DS, 1850. Set quarter section post. Tamarack 8, S.70*E., 18 links. Tamarack 8, N.57*W., 22 links. ************************************	, ,	T40N D47N41	D 44		. 11	n∟		<u></u>			
2. Property Controlling S T R R REGISTER OF DEEDS ALGER COUNTY, MI REGISTER OF DEEDS A	. 1. Public Land Survey		<u> </u>			JA:	8 11	190	39		
2. Property Controlling S T R A AGER COUNTY, MI  3. Miscellaneous S T R R Register of Deeds Stamp & File Number A Lot No. Recorded Plat Register of Deeds Stamp & File Number A Register of Deeds Stamp & File					D	DNAL.	D W.	KINI	JUNE	ΞN	
in Section  S. T. R.  Property in Sec. S. T. R.  Property in Sec. S. T. R.  Register of Deeds Stamp & File Number  4. Lot No.  Private Claims  In a field survey on December 2, 19.98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, stabilished, monumented, recovered, found as expressed below.  NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  D11: P.L.S William Ives, DS, 1850. * Set quarter section post. * Tamarack 8, S.70 * E., 18 links. * Tamarack 8, N.57 * W., 22 links. ****** Right of Way and Track Map, D.S.S.&A. Railway Company, Mackinaw Division, June 30, 1916. * No corner or track station shown. * Alger County Road Commission Records, File 16-2. ***** Michigan Department of Transportation, Projects, Seney-Munising Road, and Highway M-28, 1948 to present. * No corner shown. North-South quarter line station shown as approximate, 445+78. * Alger County Road Commission Records, File 10-1. ****** No other record of restoration.	2. Property Controlling S T R					REGIS	STER C	)F DE	EDS		
A. Lot No, Recorded Plat	in Section S	TR				ALGE	in coc	# <b>411</b> ,	, MAI		
4. Lot No		- I R			Panieta	r of De	aede S	tamn	. R Fi	le Nur	mber
I, Robert L Jamros , in a field survey on December 2 , 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below.  NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  D11: P.L.S William lives, DS, 1850. * Set quarter section post. * Tamarack 8, S.70 °E., 18 links. * Tamarack 8, N.57°W., 22 links. ****** Right of Way and Track Map, D.S.S.&A. Railway Company, Mackinaw Division, June 30, 1916. * No corner or track station shown. * Alger County Road Commission Records, File 16-2. ****** Michigan Department of Transportation, Projects, Seney-Munising Road, and Highway M-28, 1948 to present. * No corner shown. North-South quarter line station shown as approximate, 445+78. * Alger County Road Commission Records, File 10-1. ***** No other record of restoration.	• •			·	registe						
I, Robert L. Jamros , in a field survey on December 2 , 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, monumented, recovered, found as expressed below.  NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  D11: P.L.S William Ives, DS, 1850. * Set quarter section post. * Tamarack 8, S.70°E., 18 links. * Tamarack 8, N.57°W., 22 links. ****** Right of Way and Track Map, D.S.S.&A. Railway Company, Mackinaw Division, June 30, 1916. * No corner or track station shown. * Alger County Road Commission Records, File 16-2. ****** Michigan Department of Transportation, Projects, Seney-Munising Road, and Highway M-28, 1948 to present. * No corner shown. North-South quarter line station shown as approximate, 445+78. * Alger County Road Commission Records, File 10-1. ****** No other record of restoration.	4. Lot No, Recorded P	'lat		Α 1 Γ	ВС	D E	F	3 H	I_	J K	<u> </u>
state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below.  NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  D11: P.L.S William Ives, DS, 1850. * Set quarter section post. * Tamarack 8, S.70 °E., 18 links. * Tamarack 8, N.57 °W., 22 links. ******* Right of Way and Track Map, D.S.S.&A. Railway Company, Mackinaw Division, June 30, 1916. * No corner or track station shown. * Alger County Road Commission Records, File 16-2. ****** Michigan Department of Transportation, Projects, Seney-Munising Road, and Highway M-28, 1948 to present. * No corner shown. North-South quarter line station shown as approximate, 445+78. * Alger County Road Commission Records, File 10-1. ****** No other record of restoration.				2	-6-	5	4	3	+	- 2	1 -
state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below.  NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  D11: P.L.S William Ives, DS, 1850. * Set quarter section post. * Tamarack 8, S.70°E., 18 links. * Tamarack 8, N.57°W., 22 links. ******* Right of Way and Track Map, D.S.S.&A. Railway Company, Mackinaw Division, June 30, 1916. * No corner or track station shown. * Alger County Road Commission Records, File 16-2. ******* Michigan Department of Transportation, Projects, Seney-Munising Road, and Highway M-28, 1948 to present. * No corner shown. North-South quarter line station shown as approximate, 445+78. * Alger County Road Commission Records, File 10-1. ****** No other record of restoration.				3 -			-			++	-
state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below.  NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  D11: P.L.S William Ives, DS, 1850. * Set quarter section post. * Tamarack 8, S.70 °E., 18 links. * Tamarack 8, N.57 °W., 22 links. ****** Right of Way and Track Map, D.S.S.&A. Railway Company, Mackinaw Division, June 30, 1916. * No corner or track station shown. * Alger County Road Commission Records, File 16-2. ***** Michigan Department of Transportation, Projects, Seney-Munising Road, and Highway M-28, 1948 to present. * No corner shown. North-South quarter line station shown as approximate, 445+78. * Alger County Road Commission Records, File 10-1. ****** No other record of restoration.	a Beleval Immer	<del>-</del> (	Danauria 2 40.09 do bo	- 1	- <del>7</del> -	— e —	— 9— 	10	<b>,</b>	11-	12-
and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below.  NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  D11: P.L.S William Ives, DS, 1850. * Set quarter section post. * Tamarack 8, S.70°E., 18 links. * Tamarack 8, N.57°W., 22 links. ****** Right of Way and Track Map, D.S.S.&A. Railway Company, Mackinaw Division, June 30, 1916. * No corner or track station shown. * Alger County Road Commission Records, File 16-2. ***** Michigan Department of Transportation, Projects, Seney-Munising Road, and Highway M-28, 1948 to present. * No corner shown. North-South quarter line station shown as approximate, 445+78. * Alger County Road Commission Records, File 10-1. ****** No other record of restoration.	state that under requirements of P.A. 74	4, Michigan P.A. of 1970	, the comer points mentioned in line	≘s1		_		+ +		1	
by a decree of a Court of Law and /or that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below.  NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  D11: P.L.S William Ives, DS, 1850. * Set quarter section post. * Tamarack 8, S.70°E., 18 links. * Tamarack 8, N.57°W., 22 links. ******* Right of Way and Track Map, D.S.S.&A. Railway Company, Mackinaw Division, June 30, 1916. * No corner or track station shown. * Alger County Road Commission Records, File 16-2. ****** Michigan Department of Transportation, Projects, Seney-Munising Road, and Highway M-28, 1948 to present. * No corner shown. North-South quarter line station shown as approximate, 445+78. * Alger County Road Commission Records, File 10-1. ****** No other record of restoration.	and 2 above were in conformance with	regulations and rules the	refore as required in the current ma	nual 6	-18	_1/_	16-	15	,	-14-	13-
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  D11: P.L.S William Ives, DS, 1850. * Set quarter section post. * Tamarack 8, S.70°E., 18 links. * Tamarack 8, N.57°W., 22 links. ******* Right of Way and Track Map, D.S.S.&A. Railway Company, Mackinaw Division, June 30, 1916. * No corner or track station shown. * Alger County Road Commission Records, File 16-2. ****** Michigan Department of Transportation, Projects, Seney-Munising Road, and Highway M-28, 1948 to present. * No corner shown. North-South quarter line station shown as approximate, 445+78. * Alger County Road Commission Records, File 10-1. ****** No other record of restoration.	by a decree of a Court of Law and /or th	nat the comer points men	itioned in lines 3, 4 and 5 above we	re in		20	21	  :	2 <u> </u>	-23	 24-
on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  D11: P.L.S William Ives, DS, 1850. * Set quarter section post. * Tamarack 8, S.70°E., 18 links. * Tamarack 8, N.57°W., 22 links. ****** Right of Way and Track Map, D.S.S.&A. Railway Company, Mackinaw Division, June 30, 1916. * No corner or track station shown. * Alger County Road Commission Records, File 16-2. ****** Michigan Department of Transportation, Projects, Seney-Munising Road, and Highway M-28, 1948 to present. * No corner shown. North-South quarter line station shown as approximate, 445+78. * Alger County Road Commission Records, File 10-1. ****** No other record of restoration.						_				$\bot$	
A. Description of original monument and accessories and/or subsequent restoration:  D11: P.L.S William Ives, DS, 1850. * Set quarter section post. * Tamarack 8, S.70°E., 18 links. * Tamarack 8, N.57°W., 22 links. ****** Right of Way and Track Map, D.S.S.&A. Railway Company, Mackinaw Division, June 30, 1916. * No corner or track station shown. * Alger County Road Commission Records, File 16-2. ****** Michigan Department of Transportation, Projects, Seney-Munising Road, and Highway M-28, 1948 to present. * No corner shown. North-South quarter line station shown as approximate, 445+78. * Alger County Road Commission Records, File 10-1. ****** No other record of restoration.	NOTE: Not more than 2 corners, a	all in the same town an	nd range, may be recorded	10	30	2 9	2  <b>B</b>	2	7——	-26	25-
A. Description of original monument and accessories and/or subsequent restoration:  D11: P.L.S William Ives, DS, 1850. * Set quarter section post. * Tamarack 8, S.70°E., 18 links. * Tamarack 8, N.57°W., 22 links. ****** Right of Way and Track Map, D.S.S.&A. Railway Company, Mackinaw Division, June 30, 1916. * No corner or track station shown. * Alger County Road Commission Records, File 16-2. ***** Michigan Department of Transportation, Projects, Seney-Munising Road, and Highway M-28, 1948 to present. * No corner shown. North-South quarter line station shown as approximate, 445+78. * Alger County Road Commission Records, File 10-1. ****** No other record of restoration.	on this certificate.			11		<b></b>		++			+
D11: P.L.S William Ives, DS, 1850. * Set quarter section post. * Tamarack 8, S.70°E., 18 links. * Tamarack 8, N.57°W., 22 links. ***** Right of Way and Track Map, D.S.S.&A. Railway Company, Mackinaw Division, June 30, 1916. * No corner or track station shown. * Alger County Road Commission Records, File 16-2. ***** Michigan Department of Transportation, Projects, Seney-Munising Road, and Highway M-28, 1948 to present. * No corner shown. North-South quarter line station shown as approximate, 445+78. * Alger County Road Commission Records, File 10-1. ***** No other record of restoration.					31 <del>-</del>	32 	33	<del> 3</del>	4	-35	—36-  _
B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:	18 links. * Tamarack 8, N.57 D.S.S.&A. Railway Compan Commission Records, File 1 M-28, 1948 to present. * No	"W., 22 links. ***** Ri ny, Mackinaw Division 16-2. ***** Michigan D o corner shown. North	ight of Way and Track Map, , June 30, 1916. * No corner of Department of Transportation, F n-South quarter line station sho	r track stat Projects, S	eney-M	unisin	g Road	d, an	d Hig	Jhway	,
• • • • • • • • • • • • • • • • • • • •	B. Description of corner evidence	e found and/or metho	od applied in restoring or reesta	ablishing c	orner:						
D11: Located corner position by standard field survey and single proportionate measurement on line and between section corners East and West. * No original evidence remains. * Monumented the corner position as established and is accepted as a careful and faithful reestablishment of the position of the original corner.	East and West. * No original	al evidence remains. *	Monumented the comer posit	urement of ion as esta	n line a ablished	nd bet i and i	ween : s acce	section pted	on co as a	rners caref	iul
C. Description of monument for comer and accessories established to perpetuate locating the position of the comer:	C. Description of monument f	for comer and access	ories established to perpetuate	locating t	he posi	tion of	the co	mer	:		
D11: Set Berntsen aluminum monument no. AlNB30, with 3 1/4" aluminum cap, stamped to identify corner position. Established reference trees with BTsigns, blazed and scribed. Set PK nails for measure with aluminum I.D. washers in the following. * Spruce 3", S.14°E., 51.70 feet, "BT"; * Cedar 8", S.45°W., 74.33 feet, "1/4S BT"; * Tamarack 5", N.20°E., 44.22 feet, "1/4S BT"; * Tamarack 4", N.06°W., 56.65 feet, "1/4S BT"; * North face of North rail, Wisconsin Central Railroad, South, 7.82 feet. * Survey marker sign on 6 foot steel post, N.05°E., 8.0 feet. * All bearings are magnetic.	reference trees with BTsign Spruce 3", S.14°E., 51.70 f "1/4S BT"; * Tamarack 4",	ns, blazed and scribed feet, "BT"; * Cedar 8", N.06°W., 56.65 feet,	<ol> <li>Set PK nails for measure wir S.45°W., 74.33 feet, "1/4S BT "1/4S BT"; * North face of North</li> </ol>	th aluminu *; * Tamar h rail, Wis	m I.D. v ack 5", consin	washe N.20° Centra	rs in th E., 44.	ne fol .22 fe	llowin eet,	ig. *	
Signed by Liliant James Date December 16, 1998	<u> </u>	t S. James	<u>.                                    </u>	Date <u>₽</u>	eces	nbe	v /	6,	19	198	
Surveyor's Michigan License No. 25849	Surveyor's Michigan License No.	258	849								
* ROBERT L. ** FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN 20		OBERT L.	FORM APPROM	ED BY MICHIGA	NSTATE B	OARD OF	PROFESS	SIONAL	SURVE	Yors, J	AN. 28,