Approved by Alger County Land Survey Remonumentation Peer Group Under Act 345 of P.A. of 1990 On 12-12-19 55 Guldielalso

Chairman

JAN 2 3 1996

## COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

4-352

nd FILED

5p.m. प्रोडिन, County Clark ८८ - . २४, ४४

Stamp & File Number

For corners in			······································	4		
Alger (County)	Located	n;	Corner Code #	/		
Public Land Survey	т <u>4</u> т <u>—</u>	N R <sup>22W</sup> 6N R Z2W R	K13 K1	RECID 8		
2. Property Controlling in Section	s	R		DCTTT LA NUO.		
3. Miscellaneous Property in Section		R R		Register of Deeds		
Lot No  Private Claims	, Recorded Plat			A B C D		

, Robert L. Jamros	, in a field survey on	July 05, 1995	, 19,
	er requirements of P.A. 74, Micl		
in lines 1 and 2 above were	e in conformance with regulatio	ns and rules therefore as	required in the current
manual of survey instruc	ctions of the United States	Department of the inte	rior, Bureau of Land
Management or by a decre	ee of a Court of Law and/or that	at the comer points ment	tioned in lines 3, 4 and
5 above were in conforma	ance with the rules of the Micl	higan Board of Profession	nal Surveyors or by a
Decree of a Court of Law;	established, re-established, m	onumented, re-monumer	nted, recovered, found

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A	В	С	D	E	F	G	H	J_	ΚI	L_
2		$\perp$	-5-		4-	Ţ	_3	2-		_
3	-	-	+	┿	╀	╄			-	ļ.
4	-∤-	+	 	+-	ģ	+	-10	<del>-</del> ,		2-
5	+	+	+	+-	╀	+-	+-			_
6	—18-	+	-17-	+-	16	+	-15	14-	+-1	3— 
ᆉ	+-	+	+	+-	╁	+	+-		+-	_
	—19- I	╁	-20 I	+-	21 — I	†	-22-— 	23-	<del></del> 2	4
카	$\top$	$\dagger$	+	$\dagger$	-	T	+-		+	
10	–зо- I	T	-29 <b>-</b> -		28 	T-	-27-— 	26-	2	5— 
11 -			-32-		1		34	35-		-
13			_ <del></del>		33 <b>–</b> 		Ĭ	35-	Ĭ	6

A. Description of original monument and accessories and/or subsequent restoration:

K13: PLS-William A. Burt, DS, 1841, Set post corner of sections 35 & 36 - Maple 14", N.50 E., 3 links, Hemlock 6", N.10 W., 12 links. Alfred Millard, DS, 1852, recovered corner position during the GLD subdivision of T.46N., R.22W., added the following references. Hemlock 18", S.38 W., 50 links, Sugar 8", S.68 E., 35 links. William F. Bowman, RLS, 1990, Recovered a brass cap iron and remains of the GLO witnesses. Established new references. Hemlock 14', N.85 E., 12.5', 8eech 7', S.05 E., 16.7', Beech 14', N.68 W., 9.9', Maple 14", S.46 W., 20.5', Sign Post, S.00W., 2.5'. Recorded in filling No. 4-131, Alger County Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K13: Found 2" cast iron bar with 3 1/4" brass cap stamped to identify corner position dated Nov. 9, 1910. A search was made at GLO bearing tree locations, inconclusive. Found all reference trees and four inch post with sign as recorded in LCRC Report by William F. Bowman, LS, 1990. Corner position is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for comer and accessories established to perpetuate locating the position of the corner:

K13: Stamped P.A. 345 in brass cap of cast steel monument. Renewed existing reference trees w/ BT signs and paint. Set PK nails for measure m/ Alum. I.D. washers in the following reference trees. Ex. Hemlock 14°, N.87 E., 12.50 feet, " S36 BT ", Ex. Beech 7°, S.05 E., 16.66 feet, " S1 BT ", Ex. Beech 14", N.68 W., 9.83 feet, " S35 BT ", Ex. Maple 14", S.46 W., 20.45 feet, " S2 BT ", 4" Post w/ sign, South, 2.5 feet. All bearings are magnetic.

PED LAND

Board of Professional Surveyors, Jan. 28, 1971 Revised May 14, 1975 Revised Jan., 1983 FORM AND OWEN BY 25849