Approved by Alger County
Land Survey Remonumentation
Peer Group Under Act 345 of P.A. of 1990 On JUNE 119 94
P.A. of 1990 On JUNE 119 94

31. 01 1000 On <u>57.7. 1</u> .0	
$\mathcal{A} = \mathcal{A} \cup \mathcal{A} \cup \mathcal{A} \cup \mathcal{A}$	
Gerald W Carlson	
Chairman	

LAND CORNER RECORDATION CERTIFICATE

Filing Dequirement of Act 74 Mich DA 1070

4-224

For corners in Alger	- •	ement of Act 74, Mich. P.	A. 1970 7 0101 7
(County)	Located In:	Corner Code ##	
			Recorded June 24, 1994
1. Public Land Survey	T46N_ R .18W	A4	at 8:00 o'clock A. M., and
	T R		Recorded in Liber 4 of Corner Re
	TR		
	T R		Now DW. Kinner
2. Property Controlling	S T R		Alger County Register of Deeds
in Section			
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S R		register of Deeds Statis & File Number
4. Lot No , i	Recorded Plat		
			A B C D E F G H I J K L N
		•	2 - 6 - 5 - 4 - 3 - 2 - 1 -
			3
			789101112-
I. Robert L. Jamros	, in a field survey onAugus	st 25, 1993 , 19	
	quirements of P.A. 74, Michigan P.A.	• • • • • • • • • • • • • • • • • • • •	الملا الملا الملا الملا الملا الملا الملا الملا
	n conformance with regulations ar	·	the 10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
•	ructions of the United States Depar a Court of Law and/or that the corne	•	-410
-	ith the rules of the Michigan Board	•	of a
	re-established, monumented, re-	d as	
expressed below:			10 30 29 28 27 26 25
NOTE: Not more than 4 c	corners, all in the same town a	nd range, may be recorded	11
on this certificate.		12 31 32 33 34 35 36	
			13
A. Description of original	monument and accessories and	d/or subsequent restoration:	
A4: P.L.S., John Burt, DS	, 1841. Set quarter Section por	st. Beech 12, S.57 E., 26.	Beech 12, N.17 W., 29. L.E. Adams, C.S.,
			of Section 12, T49N R19W. Herbert L. Fluharty,

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A4: Found 5/8° rebar badly bent with RLS cap missing, identified by recorded reference objects. Made search for original BT's. BT in Southeast position claimed by road construction. At location of BT in Northwest position found badly decayed wood in stumphole, could not identify species. Installed new 5/8" x 18" rebar with 3 1/4" Aluminum cap, of which top is 12" below road surface. Corner position is 9 feet North of centerline of gravel road and 2 feet east of N-S fence and is accepted as the best available evidence of the position of the original corner. Renewed existing references and added additional references and Survey Marker sign.

RLS, 1975, Set 5/8" x 18" re-rod w/RLS cap at extension of line from center of Section and 1/8 corner as part of survey in Section 12, T46N, R19W. Established references, 8" Maple, S.25 E., 30.33 feet, 16" Maple, N.45 E., 20.72 feet, 9" Maple, N.13 W., 29.98 feet.

CA4: Description of monument for corner and accessories established to perpetuate locating the position of the corner: cap stamped to I.D. corner position.

Renewed existing and Est. new reference trees w/BT signs, blazed, scribed and painted. Set PK nails for measuring w/brass I.D. in the following reference trees. Exist - Maple 22", N.43 E., 20.85 feet, "1/4S". Exist - Transformer Power Pole, S.11 W., 29.09 feet, "BT". Exist - Tri-Maple 6"-7"-9", N.12 W., 29.97 feet, "BT". Maple 6", S.27 E., 35.13 feet, "1/4S-BT". Sur. Marker sign,

Surveyor's Michigan License No

Recorded in corner record No. 71 A.C. Records.

_ Date _ 1 June, 1994