Approved by Alger County Land Survey Remonumentation Peer Group Under Act 345 of P.A. of 1990 On SUNE 1994 Musla Walson Chairman
For corners in
Alger

LAND CORNER RECORDATION CERTIFICATE

Chairman	Filing Requir	rement of Act 74, Mich. P.A. 1	970
For corners in		1	
(County)	Located In:	Corner Code ##	
4 5 1 1 1 1 0	T D	25	Recorded June 24, 1994 at 8:00 o'clock A. M., and
Public Land Survey	T <u>46N</u> R <u>18N</u> T R		Recorded in Liber 4 of Corner Rec
	T R		on Page 230
	T R		Dw OW. Kinner
2. Property Controlling	S T R		Alger County Register of Deeds
in Section	S T R		
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S R		
4. Lot No,	Recorded Plat		A B C D E E C W I I K I
			A B C D E F G H I J K L
			2 - 6 + 5 + 4 + 3 + 2 + 1
			3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
		L 40 4000 40	4 7 4 8 4 9 10 10 11 11 11
	, in a field survey on0ctorequirements of P.A. 74, Michigan P.A.		
in lines 1 and 2 above were	in conformance with regulations ar	nd rules therefore as required in the	V 18 17 1 -16 15 14 14 13
	structions of the United States Depart of a Court of Law and/or that the corne		
	with the rules of the Michigan Board		20 - 21 - 22 - 23 - 24
Court of Law; established,	re-established, monumented, re-		
expressed below:			10 30 29 28 27 26 25
NOTE: Not more than 4 on this certificate	corners, all in the same town a	nd range, may be recorded	11 12 31 32 33 36 36
on this certificati	5.		12 31 32 33 34 35 36
A. Description of origina	Il monument and accessories an	d/or subsequent restoration:	
D5: Began at BT corner, position. Continued on c temp 1/4 section post corremains of W. Pine stump down under 6° of muck belinstalled monument. Corn	corrected compass line on G.L.O. rected position and searched for in northeast position. In marki ow 10° of water in open Spruce m	corrected compass line on G.L.O Bearing to corner of Sections 7, BT positions. Found remains of ng off corner location from rema arsh. At point end of post and	hing corner: Bearing west, set temp post at corner 8, 17 & 18 and marked random falling. At Hemlock in stump hole, southwest position and ins of original 87's, found 3 1/2" cedar post location established by original BY remains, and is accepted as a careful and faithful
C. Description of monum 05: Set 2 1/4 x 30 Alu w 3 1/4 Aluminum cap sta corner position. Est. re W/8I signs, blazed, scrib Set PK nails for measurin washers in the following trees. Maple 6", S.52 E. "1/4S-BI". W. Pine 13", feet "1/4S-BI". Maple 10 28.61 feet "1/4S-BI". Ma W., 29.02 feet "1/4S-BI". sign, N.29 W., 0.90 feet.	eference trees and painted. ag w/brass I.D. reference , 27.50 feet N.63 E., 29.07 ", N.73 W., ple 7", S.42 Survey Marker	established to perpetuate locatir	g the position of the corner:
	Celut S. James	Date	1 Juna, 1994
Signed by	1		- Goring ! I F
Surveyor's Michigan Licen	\$e No	FORM	APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19 REVISED MAY 14, 19

EYORS, JAN. 28, 1971 EVISED MAY 14, 1975 REVISED JAN., 1983