

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T.47.. NR.17W...

-----Alger----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 8, 9, 16, 17

DESCRIPTION OF CORNER MONUMENT $1\frac{1}{2}$ " iron pipe with $2\frac{1}{2}$ " brass cap

WITNESSES TO CORNER 14" Cedar N 48° E 35 links

6" Cedar S 87° E 31 links

12" Cedar N 20° W 82 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed Section Corner, found $1\frac{1}{2}$ " iron pipe with $2\frac{1}{2}$ " brass cap.

One Cedar B.T. in good condition (down).

Corner found by Forestry Division Survey Crew while making ~~ore~~ survey of this area.

No new pipe set.

Corner re-witnessed Sept. 14, 1956

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 10/17/56
REGISTERED LAND SURVEYOR