Cons. 4047 4/86

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T 47. NR \_ 17. . W

				Alg_e_r_		_ COUNTY
DESCRIPTION	O	F CORNER	Section corr	er common to S	ections 19, 20	0,_29,_30_
			MONUMENT			
WITNESSES	то	CORNER .	10"_Cedar	_ (a 10 mbī)	N_56° W	34 1/2 Links
			6" Cedar			
				. <b></b>		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-witnessed. Corner checks with down Tamarack B.T. in fair condition. Tamarack 10", N 60° %, 36 Links. Found Iron Pipe in place, set by waknown surveyor.

Corner was placed and witnessed August 3, 1960.

SURVEYORS SEAL

SIGNED SILLY DATE 8/12/60 DATE