SURVEY & BEMONUMENTATION

Approved by Alicar Gourdy Land Survey Nemerous strain Peer Group Under Add 016 of P.A. of 1990 Cn. 12-10, 1097.

FEB 1 9 1998

05-52

.A. 01 1003	Colon Transfer of the Colonial
u	ld w Carlson
713.	VIV (1) AA I AA
	Ch - Layer may
2	فانتائه المتانية

SECTION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	Located in:	Corner Code #	
(County)			F:L ED
Public Land Survey	48 15 T <u>488</u> R <u>188</u> T R T R	G 2-	TIME <u>8:30 A.m.</u> DEC 17 1997
 Property Controlling in Section Miscellaneous Property in Section 	T R S T R S T R S T R		DONALD W. KINNUNEN REGISTER OF DEEDS REGISTER COUNTY, MI Register of Deeds Stamp & File Number
5. Private Claims I, Robert L. Jamros do hereby certify that under req in lines 1 and 2 above were in comanual of survey instructions Management or by a decree of 5 above were in conformance Decree of a Court of Law; estal as expressed below:	, in a field survey on	of 1970, the corner points mentioned es therefore as required in the current of the Interior, Bureau of Land er points mentioned in lines 3, 4 and rd of Professional Surveyors or by a d, re-monumented, recovered, found	2 6 5 4 3 2 3 3 4 3 5 36 5 36 5 4 5 3 4 3 5 36 5 5 4 5 3 4 3 5 36 5 5 4 5 5 4 5 5 5 6 6 18 17 16 15 14 13 12 12 12 12 12 12 12 12 12 12 12 12 12
·	monument and accessories and		13 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

G2: PLS - George E. Adair, OS, 1851 * Set quarter post * Beech 8, N.30 W., O7 links * Beech 6, S.59 1/2 E., 41 links ***** J.F.

Radcliffe, RLS, C.C.I. Co., Forestry Simision, 1951 * Set post at corner position from Government Beech 87's, No witness's * Chrecorded ***** Ray J. Brotherton, RLS, C.C.I. Co., Forestry Division, 1952 * Recovered and replaced post set by J.R. Radcliffe with a new 6 inch fir post * Established reference trees * Crotched Maple 16, N.29 E., 6 links, sortices NBT * Beech 12, S. 4 links, scribed NBT * Unrecorded. ***** Dean C. DelaMater, FLS, Michigan Department of Conservation, 1983 * 1 original BT still in place, in fair condition * Rèplaced exist, post with 1 inch gaiv. Iron pipe w/4 inch brass cap * References to corner - Sugar Maple 20, N.28 E., 6 links * Beech 12, S.05 E., 3 links * Recorded in Liber 2, Page 72, Alger County records. ***** Goodbar subsequent restoration on record.

B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:

32: Found 1 inch galv. From pipe w/brass cap. * Recovered 2 exist. BT's from 1952 innecorded report and 1953 recorded report a Established new reference trees * Monument position as found is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

32: Exist. 1 inch galv. From pipe wydraes dap as stamped to identify corner position a Renewed exist. reference tree wyBT signs and paint a Established additional reference trees wyBT signs, blazed, scribed and painted a Set PK nails for measure wyAlum. F.D. washers in the following - Beech 4, N.68 E., 27.20 feet, 1/48 BT a Exist. BT, Beech 14, E.D. W., 2.67 feet, no marks visible and Maple 5, S.47 W., 19.24 feet, 1/48 BT a maple 6, N.59 W., 10.23 feet, 1/48 BT a Survey marker sign on 6 foot steel post, S.72 W., 1.2 feet all bearings are magnetic.

Signed by falled Surveyor's Michigan License No. Z5849

_ Date <u>/ Z //0 /</u>

VED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

ACCIONT 1 JAMBOS EBOFECCION