DEC 2 7 1999

For corners in CTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Alger County Land Survey Remonumentation Peer Group Under Act 345 ct P.A. of 1990 On
Guldalousa
Chairman

05-	1	7	6

Alger	Loca	ated In:	Corner Code #				00	,- , , ,
(County) 1. Public Land Survey		T <u>48N</u> R <u>15W</u> T R		-		//3c	pa	h.
 Property Controlling in Section Miscellaneous Property in Section 	s s	T		_	DONALE REGIS	1 5 199 W. KINN TER OF DE R COUNTY, Stamp & F	IUNEN Eds Mi	
4. Lot No, 5. Private Claims,	Recorded Pla	ıt			A B C 5) E F G	H -3	J K L M
do hereby state that under rein lines 1 and 2 above were in manual of survey instructio Management or by a decree 5 above were in conformant Decree of a Court of Law; es as expressed below:	equirements of conformance vents of the United to Court of Late with the rules	P.A. 74, Michigan F with regulations and ted States Depart aw and/or that the o s of the Michigan I	P.A. of 1970, the corner points rules therefore as required in ment of the Interior, Burea corner points mentioned in lin Board of Land Survey	s mentioned the current au of Land	5 6 — 18 — 1 7 8 — 19 — 2 9 10 — 30 — 2	0 21		14 13 13 12 13 12 13 13 14 15 15 15 15 15 15 15 15 15 15 15 15 15
NOTE: Not more than 2 con this certificate.			nd range, may be recorded		11 3 3	2 33	34-	35 36

A. Description of original monument and accessories and/or subsequent restoration:

G6: PLS * George E. Adair, DS, 1851. * Set quarter section post. * Hemlock 12", N.49 E., 46 links. * Hemlock 9", S.60.5 W., 22 links. ***** Michigan Department of Conservation, Forestry Division. * Dean C. DeLaMater, RLS, 1951. * This corner was established by proportionate measurement while making a partial resurvey of this township. * Set 1" iron pipe with 4" brass cap. * 26" W.Pine stump, S.55 E., 118 links. * 12" H.Maple, S.48 W., 245 links. * Liber 2, Page 5, Alger County Corner Records. ****** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

66: Located corner search area by calculated position and standard field survey methods. Found 1' iron pipe with 4' brass cap. Also found both BT's of the 1951 report in good condition. Corner position as found lies 2.3 feet east of line and 0.9 feet south of proportional position between section corners 1/2 mile north and 1/2 mile south. Renewed existing references and established additional references. Existing corner monument as found is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

66: Existing 1" iron pipe with 4" brass cap. * Renewed existing references with BT signs and paint. * Established new reference trees with BT signs, blazed, scribed and painted. * Set PK nails with aluminum I.D. washers for measure in the following: Existing - 26" W.Pine stump, S.48.5 E., 77.72 feet. * Existing - 24" H.Maple, S.52.5 W., 161.72 feet. * W.Pine 12", N.51 E., 228.95 feet, "1/4s BT". * 18" H.Maple, N.52 W., 281.82 feet, "1/4s BT". * Survey marker sign on 6 foot steel post, S.29 W., 1.5 feet. * All bearings are

Date_

magnetic.

	Dan	61
Signed by	Rebut C	I femos
Surveyor's Michigan Light	, ense No	25849

ROBERT L.

JAMROS
PROFESSIONAL
SURVEYOR
No.
359499