SURVEY & REMONUMENTATION

Approved by Alger County
Land Survey Remonumentation
Peer Group Under Act 245 of
P.A. of 1980 On 5/8 1996

Heald Wulso

JUL 3 0 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

4-381

Chairman For corners in	Filing Requi	rement of Act 74, Mich. P./	A. 1970 FILED
Alger (County)	Located in:	Corner Code #	TIME 3:00 p.m .
1. Public Land Survey	T <u>48N</u> R <u>15N</u> T R		JUN 27 1996
	T R T R		DONALD W. KINNUNEN REGISTER OF DEEDS
Property Controlling in Section	S T R S T R		ALGER COUNTY, MI
Miscellaneous Property in Section	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No, F	Recorded Plat		A B C D E F G H I J K L M
5. Private Claims			
			3
			4 7 8 9 10 11 12 -
		otober 27, 1995 , 19	
do hereby certify that under red in lines 1 and 2 above were in d	V 18 1 1/ 1 1 10 10 10 10 14 14 13 13 13 13 13 13 13 13 13 13 13 13 13		
manual of survey instruction:	Land 7		
Management or by a decree of 5 above were in conformance	thus		
		ented, re-monumented, recovered,	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			11
			131

A. Description of original monument and accessories and/or subsequent restoration:

69: PLS-George £. Adair, DS, 1851, Set post corner of sections 21-22-27-28, W.Pine 30*, N.40 1/2 E., 20 links, Hemlock 18*, S.40 1/2 W., 40 links.**** Department of Conservation, Forestry Division, Dean C. DeLamater, RLS, 1954, This corner was found by forestry division survey crew, while making a partial resurvey of this township. Two original BT's still in place, one in fair condition, one in poor condition. Set 1' pipe with 4' brass cap and established the following references, W.Pine Stump 28', N.28 W., 52 links, W.Pine Stump 30", S.39 W., 45 links. Filing No. 63, Alger County Records. No other subsequent restoration.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G9: Found one inch galvinized iron pipe with four inch brass cap and five inch squared post, scribed. Also found was two existing BT's, White Pine stumps as stated in 1954 report. Existing monument was set, as stated in 1954 report, from two original BT's still in place, one in fair condition, one poor, - are now obliterated. Corner position has been verified against corners West and South. Monument as set is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G9: Stamped P.A. 345 in existing four inch brass capped Department of Conservation Monument. Established new reference trees w/ BT signs, blazed, scribed and painted. Set PK mails for measure w/ Alum. I.D. washers in the following reference trees, W.Pine 10", N.40 E., 14.78 feet, " S22 BT ", W.Pine 9", S.57 E., 65.73 feet, " S27 BT ", Maple 12", S.50 W., 73.23 feet, " S28 BT ", W.Pine 6", N.28 W., 34.81 feet, " \$21 BT ', Survey marker sign on six foot steel post, N.69 E., 1.0 feet. All bearings are magnetic.

Signed by Surveyor's Michigan License No.

Date

258AB TOPESSIONE FORM APPROVED BY MICHIGAN STATE BOX

FESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

ROBERT L. **JAMROS PROFESSIONAL** SURVEYOR No.