DEC 2 7 1999

For	cor	ners	in

Alger

5. Private Claims _

LAND CORNER RECORDATION CERTIFICATE

Approved by Aiger County Land Survey Remonumentation
Peer Group Under Act 345 of P.A. of 1990 On 12-8 1997
Guella Calson
Chairman

For	corners	i

ECTION	Filing Rec	uirement of Act 74, Mich. P.A. 197	7(
	Located In:	Corner Code #	

70	Chairman
	05-175
	1 1644
	TIME
	DEC 1 5 1999
	DONALD W KINNUNEN

48N R 15W Ţ 1. Public Land Survey T 44N R 15W _ R _ T __ R _ 2. Property Controlling __т _ R REGISTER OF DEEDS S in Section T _ R_ 3. Miscellaneous Property in Section __ , Recorded Plat_

ALGER COUNTY, MI													
Regist	ter c	of D	ee	ds S	Sta	mp	& F	ile	Νι	ımk	er		
	A	В	С	D	E	F	G	н	1	J	к	ı	M
		Т		T	Т		T			T		Ŧ	

Robert L. Jamros	, in a field survey on	October 20,	1999	_ , 19,
do hereby state that unde	r requirements of P.A. 74, Mich	nigan P.A. of 1970,	the corner	points mentioned
in lines 1 and 2 above were	in conformance with regulation	ns and rules theref	ore as requ	ired in the current
manual of survey instruc	tions of the United States I	Department of th	e Interior,	Bureau of Land
Management or by a decre	e of a Court of Law and/or that	at the corner points	s mentione	d in lines 3, 4 and
	nce with the rules of the Mich			Surveyors or by a
	established, re-established, mo			recovered, found
as expressed below:				

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	В	C D	E I	F G	н	J	K	. N
2	-é —		1-4	-	3	 2-		_
3		┼-┼-			-	-		<u> </u>
4	- 7 —			,	10-	11-	 1	l 2—-
5 —	-	1-+		-		\vdash		<u> </u>
6	-18-	17		6	15-	14-	 	เ 3—-
7	-	┦╾┼	_	_	-	- -		
8	-19-	20	2	1	22-	-23-	- - 2	 4
9	- -				 -		_}-	<u> </u>
10	-30 -	- 29		8	-27	-26-	2	 !5—-
11	\bot	14	-	-	-		-	
12	-31 <i>-</i>		3	3	 ∙34—	 35-	 	1 36—
131_		لـــــــــــــــــــــــــــــــــــــ				<u> </u>		L

A. Description of original monument and accessories and/or subsequent restoration:

L1: PLS * John Burt, DS, 1841. * Set quarter section post. * Beech 22", N.39 E., 05 links. * Beech 12", N.20 W., 14 links. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L1: Located corner search area by calculated position and standard field survey methods. No GLO evidence of the corner position or the BT's remain, position has been lost. Reestablished corner position at the mid point and on line between section corners 1/2 mile East and 1/2 mile West. Corner position as reestablished is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L1: Set 2 1/2"x30" Berntsen aluminum monument No. A1NB30 with 3 1/4" aluminum cap stamped to identify corner position. * Established the following reference trees with 8T signs, blazed, scribed and painted. * Set PK nails with aluminum I.D. washers for measure in the following: Beech 7", N.58 E., 18.22 feet, "1/4s BT". * Beech 6", S.21 E., 20.91 feet, "1/4s BT". * Beech 7", S.58 W., 30.76 feet, "1/4s BT". * Maple 9", N.67 W., 16.27 feet, "1/4s BT". * Survey marker sign on 6 foot steel post, S.41 E., 1.5 feet. * All bearings are

magnetic.

Signed by_ 5849 Surveyor's Michigan License No.

ROBERT L **JAMROS** PROFESSIONAL SURVEYOR No. 2987.9

OFESSIONA