Approved by Affor County Land Survey Flori claims I Life Pear Group United Add Life Pear Group United United Add Life Pear Group United Uni
P.A. of 1980 On 3-24 10 97
General Carlson
Chairman
For corners in

Pear Group United Add a 10 cl P.A. of 1990 Cn 3-24 10 97			
Heild Calson Chairman For corners in	· -	RECORDATION CERTIFICATE ent of Act 74, Mich. P.A. 1970	O • 7
ALGER - SCHOOLCRAFT (County)	Located In:	Corner Code #	FILED
1. Public Land Survey	T 48N R 16N T 47N R 16W T R	F13	TIME 2!00 pm MAR 3 1 1997
in Section S _ 3. Miscellaneous S _	T R T R T R T R T R	Re	DONALD W. KINNUNEN REGISTER OF DEEDS ALGER COUNTY, MI egister of Deeds Stamp & File Number
4. Lot No, Recorde 5. Private Claims	d Plat	<u>.</u>	A B C D E F G H I J K L
I, Robert L. Jairos , in a field survey on Julie 07, 1996 , 19 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:			4 - 7 - 8 - 9 - 10 - 11 - 12 - 5 - 14 - 13 - 7 - 16 - 15 - 14 - 13 - 7 - 16 - 15 - 22 - 23 - 24 - 9 - 10 - 30 - 29 - 28 - 27 - 26 - 25 - 11
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			12 31 32 33 36
A. Description of original monum		•	TATN. R.16W. FI Schoolcraft Co.

subsequent restoration found.

B. Description of comer evidence found and/or method applied in restoring or reestablishing comer:

F13: Found 20° dead Beech stub (15' high) in N.13 W. GLO position. Old blaze scars around tree at eye level. GLO blaze scar open and deep with portions of measuring notch still visible. Set corner position at S.13 E., 26 links from GLO measuring notch. There is a 12° Maple paint marked 1/4 S approx. 8 feet southerly of corner position w/ blaze lines running East and West. This corner position was recovered during the Section Subdivision Survey of Section 4, T.47N., R.16W. Monument as set is accepted as a careful and faithful perpetuation of the position of the original corner.

SURVEY & REMONUMENTATION

AUG 1 5 1997

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F13: Set Berntsen Monument No. A1N830, stamped to identify corner position. Established reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure w/ Alum. I.D. washers in the following reference trees. * Maple 16", S.64 W., 18.93 feet, * 1/4S BT* * Maple 12", N.30 W., 13.23 feet, "1/45 BT" * Maple 6", N.67 E., 26.54 feet, "1/45 BT" * Maple 5", S.21 E., 28.73 feet, "1/45 BT" * Survey marker sign on six foot steel post, \$.44 E., 1.0 feet. * All bearings are magnetic.

Surveyor's Mighigan License No

JAM<u>ROS</u> PROFESSIONAL

Date

March, 1997

25849 OFESSION

LIGVEYO No.