SURVEY & REMONUMENTATION

Approved to the County Land Survey He to the or of sign Peer Group United Approved Staff P.A. of 1990 On 12-10-1997

Mereld W Cerlan

Chairman

FEB 1 9 1998

05-89

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

For corners in	9		* " **
(County)	Located In:	Corner Code #	F.LED
Public Land Survey	49 13 T <u>49</u> R <u>14</u> 1 T <u>49</u> R <u>14</u> 1 T R	<u>M6</u>	TIME <u>Stad A.M.</u> DEC 17 1997 DONALD W. KINNUNEN
 Property Controlling in Section Miscellaneous Property in Section 	T R S T R S T R S T R S T R		REGISTER OF DEEDS GER COUNTY, MI Register of Deeds Stamp & File Number
f. Recent Leaves do hereby certify that under requirements 1 and 2 above were in command of survey instructions Management or by a decree of 5 above were in conformance Decree of a Court of Law; esta as expressed below: NOTE: Not more than 4 conformance than	, in a field survey on	A. of 1970, the corner points ment rules therefore as required in the cornent of the Interior, Bureau of omer points mentioned in lines 3, loard of Professional Surveyors of inted, re-monumented, recovered,	2 -6 -5 -4 -3 -2
on this certificate. A. Description of original	monument and accessories	and/or subsequent restoration	12 31 32 33 34 35 36 13 13 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

A6: PLS - John Eurt, DS, 1841 * Set quarter section post * Eeech 8, S.25 E., 16 links * Beech 13, H.25 W., 22 links ***** George L. Depew, County Surveyor, 1917 * Set iron corner on true line at equal distance * No references given ***** M.D.S.H., Survey and Construction Plans for M-77, 1958 * Corner position not shown, only wire fence to East ***** Gerald W. Darlson, RLS, 1978 * Found 1/2 inch iron pipe at East edge of pavement of M-77, old broken fence to East and West * Witnesses - Hapie 5, S.43 W., 32.71 feet * Triple Maple 5, S.38 W., 84.40 feet * Power Pole, N.13 E., 92.21 feet * Recorded in Liber 1, Page 175, Alger County Corner Records ***** Neil E. Hill BLS, 1939 * Found 1/2 inch iron pipe on East edge of pavement and accepted, placed monument box * Witnesses - S.53 W., 75.70 feet, 6 Maple * S.70 W., 81.76 feet, 11 Maple * West, 85.43 feet, 12 Maple * N.10 E., 92.27 feet, Power Pole * Recorded in Liber 4, Page 50, Alger County Corner Records ***** No other subsequent restoration recorded.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A6: Found 1/2 icon Rebar w/I.D. cap no. 27447 (Neil E. Hill) in monument box, 11.6 feet East of centerline pavement on M-77 * Renewed exist. S7's and established additional references. * Measurements to corners North and South check well. Corner position is accepted and used locally. * Accepted monument at this position as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

A6: Replaced 1/2 inch Rebar with a 5/8 inch by 18 inch Recar #/Berntsen Alum. cap no. RBD 5325, stamped to identify corner position * Renewad exist. Effs W/8T signs and established additional references W/8T signs * Set PK hails W/Alum. I.O. washers for measure in the following * Exist. ET, Power Pole, N.14 E., 92.36 feet, scribed *BT* at base, no signs * Red Pine 16. 5.42 E., 55.65 feet * Maple 14. N.83 N., 66.49 feet * Exist. BT, Maple 7, S.44 N., 82.87 feet * All bearings are magnetic.

Signed by falut Amos

Surveyor's Michigan License No. 25849

Date 12/10/1997

ROTESCIONAL

SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983