SUBVEY &

nec 2 7 1999

For corners	ín	SECTION

LAND CORNER RECORDATION CERTIFICATE

Approved by Alger County Land Survey Remonumentation
Land Survey Remonumentation
Peer Group Under Act 345 of
Peer Group Under Act 345 of P.A. of 1990 On 12-8 1999
Guelduralson

marial of the second
Machson
nan

	Filing Require	ement of Act 74, Mich. P.	A. 1970 Onaminan
ALGER (County)	Located In:	Corner Gode #	05-146
Public Land Survey	T 49N R 13W T 49N R 14W	A9 1/ M9	TIME 1:30 p.m.
	T R T R		DEC 1 € 1999
 Property Controlling in Section Miscellaneous Property in Section 	S T R S T R S T R S T R		DONALD W. KINNUNEN REGISTER OF DEEDS ALGER COUNTY, MI Register of Deeds Stamp & File Number
	, Recorded Plat		
	, 11000/1001 101		A B C D E F G H I J K L M
do hereby state that under in lines 1 and 2 above were i manual of survey instructi. Management or by a decree 5 above were in conforman Decree of a Court of Law; e as expressed below:	, in a field survey onMay requirements of P.A. 74, Michigan P.A. 10 conformance with regulations and rons of the United States Department of a Court of Law and/or that the conce with the rules of the Michigan Bostablished, re-established, monument	A. of 1970, the corner points men ules therefore as required in the c tent of the Interior, Bureau of orner points mentioned in lines 3, pard of Land Surveyors o ted, recovered,	tioned 6 18 17 16 15 14 13 current Land 4 and 8 19 20 21 22 23 24 or by a
on this certificate	corners, all in the same town and e.	range, may be recorded	12 31 32 33 34 35 36 3
A9: PLS * John Burt, DS N.62 E., 26 links. ***** Michigan State Highway D	: George L. Depew, CS, 1917. * Se	et post corner of Sections 1 It iron corner according to comment Plans for M-77. * Wood	19 & 30. * Birch 6", S.46 W., 27 links. * Cedar 14", original survey notes. * No references. ***** post. * 4" Birch, S.50 W., 16.60 feet. * Birch.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A9: Established corner position using reference measurements from M.D.S.H. Improvement Plans of Highway M-77. Recovered curve P.I. of highway at Station 660+40.66 feet from references on highway plans. Established corner position as shown 312.53 feet North along tangent line and 26.72 feet West of tangent line of highway curve. Position falls on line between 2 concrete right of way markers, East and West, and 58.1 feet from centerline of highway, record is 57.96 feet. Highway plan references and wood post have been destroyed and lost. Distance by highway station to section corner to the North is 5294.25 feet, measured is 5284.90 feet. Highway station of a 36° C.M.P. culvert is 662+50 feet. Distance between culvert and section corner by station is 37 feet, found and measured as 35 feet. Corner position as established is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A9: Set 2 1/2"x30" Berntsen aluminum monument No. A1NB30 with 3 1/4" aluminum cap stamped to identify corner position. * Established the following references: Chiseled 'X' in the centerline of the East concrete headwall of the existing culvert under Highway M-77, \$.45 W., 53.63 feet. * Power pole, N.70 E., 60.00 feet with PK nail with aluminum I.D. washer for measure and scribed "BT". * W.Birch 5°, S.23 E., 7.00 feet with BT signs, blazed and scribed "BT". * Set PK nails with aluminum I.D. washer for measure. * Survey marker sign on 6 foot steel post, N.46 E., 1.5 feet. * No other references available. * All bearings are magnetic.

Signed by_ Surveyor's Michigan License No.

JAMROS PROFESSIONAL SURVEYOR Date

TE OF MICH

ROBERT L