	^-···								
			•						
L	Approved by Alger Col and Survey Remonumer Peer Group Under Act 3 A 51/1990 On Group Vision 1990 On Group Vision 1								
P.	A. 61/1990 On 5-18	45 of 19 <i>.24</i>							
	Chairman Chairman r corners in		RECORDATION CERTIFICATE	m - J/X					
750	r corners in / Alger								
	(County)	Located In:	Corner Code ##	M 26 1004					
4	Public Land Survey	T 40N D 10H	ro	Recorded May 26, 1994 at 8:00 o'clock A. M., and					
١.	rubiic Laitu Survey	T <u>49N</u> R <u>13W</u> T R	<u>£2</u>	Recorded in Liber 4 of Corner Recon Page 218					
		T R		n rage 210 ft. Our str.					
_	Daniel Cantallina	TR		Alger County Register of Deeds					
۷.	Property Controlling in Section	S T R S T R	<del></del>						
3.	Miscellaneous	S T R		gister of Deeds Stamp & File Number					
	Property in Sec.	S T R		g.o.o. o. Dood otamp a 1 no manbo					
4	Lot No	Recorded Plat							
		recorded trial		A B C D E F G H I J K L N					
				2 6 5 6 1 3 1 2 1 1					
				3					
1, <u>f</u>	Robert L. Jamros	5 1 1 1 1 1 1 1 2 -							
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the				6 18 17 16 15 14 13					
		ructions of the United States Department	·	7					
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as									
					expressed below:				10 30 29 28 27 26 25
on this certificate.				12 31 32 33 34 35 36					
				13					
A. Description of original monument and accessories and/or subsequent restoration:									
E2: P.L.S Francis Coleman, DS, 1851. Set Qr. Sec. post - Hemlock 25, N.41. W., 17 links, Cedar 16, S.40 E., 19 links. James									
Rountree, County Surveyor, 1908, iron driven according to field notes and barren trees. Alger County R.C. Corner shown on Alignment survey drawing, 1936. Billy D. Buckler, RLS, 1973, found concrete plat monument, A.C.Rec.No.31. Robert L. Jamros, RLS, 1981, found									
iron bar encased in 4° x 4° concrete, A.C.Rec.No.405. Gerald W. Carlson, RLS, 1984 found concrete monument at intersection of roads,									
A.C.Rec.No.4-16.									
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:									
E2:	Located corner position	n at the centerline of intersection	n of County Road H-58 East (Aspha)	lt) and East Bay Road. Found 1/2 inch					
E2: Located corner position at the centerline of intersection of County Road H-58 East (Asphalt) and East Bay Road. Found 1/2 inch rebar w/plastic cap no. 25849 encased in concrete 4 inches square below asphalt road surface. Installed aluminum cap on 1/2 inch rebar, renewed existing reference points and also established new reference points. Corner position is well established and is accepted as a careful and faithful perpetuation of the position of the original corner.									
_			and the first of t	a a sikina of the source					
Ç <sub>2</sub> :	Description of monume installed 3 1/4 Alum.	ent for corner and accessories est cap on exist	ablished to perpetuate locating th	e position of the corner:					

1/2" rebar in 4" x 4" conc. base and grouted around cap with cement. Stamped to I.D. corner position. Est. reference trees w/8T signs, blazed, scribed and painted. Set PK nails for measuring w/brass I.D. washers in the following

reference trees. Exist - Maple 24", N.33 E., 61.0 ft., "BT". Power Pole, N.42 W., 45.43 ft., "BT". Exist - Twin Maple, 8"-12", S.59 W., 88.79 ft., "1/4S-BT". Twin W. birch, 6"-10", S.25

Surveyor's Michigan License No.

Signed by \_

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN.. 1983

Date