SURVEY & REMONUMENTATION

Approved by Alger County Land Survey Remonumentation Peer Group Under Act 345 of P.A. of 1990 On 12-10-19 97

Chairman

usld w College

FEB 1 9 1998

05-86

SECTION LAND CORNER RECORDATION CERTIFICATE

	Filing Require	ement of Act 74, Mich. P.	A. 1970
For corners in			FiLED
(County)	Located In:	Corner Code #	
(Sound)	49 13	F3	TIME 8:30 Aum.
1. Public Land Survey	T R T R		DEC 17 1997
	T R T R		DONALD W. KINNUNEN REGISTER OF DEEDS
Property Controlling	S T R		GER COUNTY. MI
in Section	S T R		
3. Miscellaneous	S T R		Bertale of B. J. Ot. A. W. N. Okasa
Property in Section	S T R		Register of Deeds Stamp & File Number
4. Lot No, R	ecorded Plat		A B C D E F G H J K
Robert L. Jamros	in a field survey on	gust 04, 1997	5
do hereby certify that under req	uirements of P.A. 74, Michigan P.A	. of 1970, the corner points ment	tioned 6 18 17 16 15 14 13 13
	onformance with regulations and ru	•	urrent
	of the United States Departm		
	a Court of Law and/or that the co		
	with the rules of the Michigan Bo olished, re-established, monument		/ y
•	ners, all in the same town and	range, may be recorded	11

A. Description of original monument and accessories and/or subsequent restoration:

F3: PLS - Francis Colman, DS, 1851 * Set quarter section post * Hemlock 16, N.48 E., 47 links * White Birch 5, S.55 W., 20 links ****** Billy D. Buckler, RLS, 1973 * Found wood post with remains of Hemlock stump in proper position * Believe post was set by Edwin Swan, RLS, 1950 * Witnesses - Cedar 5, S.64 E., 24.6 feet * Cedar 5, N.57 E., 36.3 feet ***** Recorded in Liber 1, Page 31, Alger County Corner Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F3: Found both BT's of the 1973 recorded report, comment and wood post gone * GLO notes recorded a winding stream, 2 chains North of corner position, found to be at this time approximately 60 feet. Stream lies in wide botton plateau and is subject to relocation with seasonal changes * Found large decayed Hemlock stump in the GLO position of N.48 E., 47 links, GLO BT White Birch 6, S.55 W., 20 links, is beyond recovery * Established corner position from 1973 recorded BT's and remains of Hemlock stump * Renewed exist. BT's and established additional reference trees * Corner position accepted and used locally by adjacent properties * Corner position has been accepted and used for property surveys * Corner position from exist. BT's is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F3: Set Berntsen Alum. monument no. AINB30, stated to identify corner position * Renewed exist. BT's w/signs and paint * Established additional reference trees w/BT signs, blazed. stribed and painted * Set PK nails w/Alum. I.D. washers in the following - Exist. BT, Cedar B, S.57 E., 24.82 feet, dbl. blzd. * Exist. BT, Cedar 9, N.62 E., 36.26 feet, dbl. blzd. * Cedar 6, N.72 E., 0.84 feet, "1/45 BT" * Balsam 10, S.47 W., 20.12 feet, "1/45 BT" * Elstey marker sign on 6 foot steel post, S.30 E., 1.25 feet * All bearings ar magnetic.

Signed by Jaluat Amus
Surveyor's Michigan License No. Z5849

___ Date____/Z//0/

RODERT L.

JAMROS
PROFESCIONAL
19 STIVEYOR

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975

EVISED MAT 14, 1975 REVISED JAN., 1983