SURVEY & REMONUMENTATION

Approved by 1 tot County Land Survey Flamon unanguion Peer Group Lazar Act 345 of 12-10 1991 P.A. of 1990 Ca_

Chair

FEB 1 9 1998

SECTION LAND CORNER RECORDATION CERTIFICATE

05-3	85 T
------	------

Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Corner Code # Located In:

muED

	County			TIME _ 8:30 A.M.		
1.	Public Land Survey	49 13 T <u>191</u> R :: T R		DEC 17 1997		
2.	Property Controlling	T R T R S T R		DONALD W. KINNUNEN REGISTER OF DEEDS GER COUNTY, MI		
3.	in Section Miscellaneous	S T R S T R				
	Property in Section	S T R	-	Register of Deeds Stamp & File Number		
		Recorded Plat		A B C D E F G H I J K L M		
do in l ma	to hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and					
5 a De	above were in conformance	of a Court of Law and/or that the c se with the rules of the Michigan B tablished, re-established, monumer	Board of Professional Surveyors or	or by a , found 10 33 - 29 - 28 - 27 - 26 - 25		
NC	OTE: Not more than 4 c on this certificate.	corners, all in the same town and	d range, may be recorded	11		
A.	Description of origina	al monument and accessories	and/or subsequent restoration	on:		

G2: PLS - Francis Colman, DS, 1951, Set quarter section post - White Birch 4, N.35 W., 36 links * Yellow Fine 4, S.69 E., 25 links.***** 7.3. McLaren, 1949, C.C.I. Co., Forestry Division * Indicates a 6 inch squared post on Lang and Timber Report, unrecorded ****** Thomas 9. 1'Erien, RLS, 1992 * Found 1/2 inch pipe at a position South of GLO distance from the partnesst corner of section, no GLO evidence evident # Unrecorded report **** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G2: Found 1 into this pipe by field survey, South of proportioned corner position * Existing iron pipe measures well to East line of recorded Plat of AGATE POINTE No. 2, being part of Section 4, Township 49 North, Range 13 West and Section 33, Township 50 North, Range 13 West # A recorded survey of the Southwest quarter of Section 4 measures very well to the existing iron pipe position. L.1,P.31, Alger County corter records. Surveyed by Billy D. Buckler, RLS, 1973 * The collateral evidence supports the existing pipe position as being accepted and used * Existing corner is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G2: Installed ther exist, pipe a Berntsen Alum, monument caping. A1NB30, stamped to identify corner position * Established reference trees with BT signs, plazed and scribed * Set PK mails w/Alum. I.D. washers for measure in the following - Red Pine 6, N.47 W., 10.15 feet, "1/45 BT" = Feb Pine 4, N.62 E., 12.39 feet, "37" * Jack Pine 10, S.40 W., 8.92 feet, "1/45 BT" = Feb Pine 16, S.41 W., 37.20 feet, 11/48 ETT = Europy marker sign on 6 foot steel post, South, 1.10 feet * All bearings are magnetic.

			$\overline{}$
Signed by	Cahut	S	(cimus
-	Higan License No	/	25849

Date AN STATE BOARD OF PROFESSIO FORM APPROVED BY MIC

T L 23 ONA**L**

> SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983