SURVEY & REMONUMENTATION

Approved by Alger County Land Survey Remonumentation Peer Group Under Act 845 cf P.A. of 1990 Cn 12-10 13 97

FEB 1 9 1998

erall W Carles

SECTION LAND CORNER RECORDATION CERTIFICATE

05-80

Chairmon Filing Requirement of Act 74, Mich. P.A. 1970

38.:	Located In:	Corner Code #	FLID
(County) 1. Public Land Survey	49 13 T <u>29</u> R <u>22</u> T R T R		TIME _ 8'30 Ans
Property Controlling in Section Miscellaneous Property in Section	S T R S T R S T R S T R		DONALD W. KINNUNEN REGISTER OF DEEDS GER COUNTY, MI Register of Deeds Stamp & File Number
5. Private Claims	Recorded Plat		2 6 5 4 3 2 1 1 2 1 2 1 1 1 1 1 2 1 2
do hereby certify that under re in lines 1 and 2 above were in a manual of survey instruction Management or by a decree of above were in conformance	, in a field survey on	A. of 1970, the comer points menti- rules therefore as required in the cu- nent of the Interior, Bureau of I orner points mentioned in lines 3, 4 oard of Professional Surveyors or	oned 6 18 17 16 5 14 13 13 14 13 14 15 14 15 14 15 15 14 15 15 15 14 15 15 15 15 15 15 15 15 15 15 15 15 15
NOTE: Not more than 4 comers, all in the same town and range, may be recorded on this certificate.			12 31 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

16: PLS - Francis Colman, SS. 1851, Set quarter section post - Sugar 10, N.27 W., 28 links * Sugar 9, S.39 E., 10 links * J.R. Radcliffe and G.A. Moote, C.C.I. Co., Land and Timber Report, 1957 * Indicate post at corner position ***** No other subsequent restoration.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

16: Located corner position by field survey. Position lies in high open hardwoods * Found cruisers tally tree with clazes and hacks in all quadrants, N.54 E., 10 feet from located corner position. * Paint lines running North and West from corner postics, so evidence of post found * Established corner position on true line at mid point between section corners North and South * Corner positioin is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

I6: Set Berntsen Alum. manuzent no. AINB30, stamped to identify corner position * Established reference trees W/BT signs, blazed, scribed and painted * Set 3% fails w/Alum. I.D. washers for measure in the following - Maple 4, N.29 E., 23.45 feet '1/48 BT' * Maple 11, S.74 E., 25.77 feet, "1748 BT" * Maple 6, S.18 E., 21.77 feet, "1748 BT" * Maple 6, S.68 W., 17.75 feet, "1748 BT" * Survey marker sign on 6 foot steel post, 3.31 E., 2.0 feet * All bearings are magnetic.

Surveyor's Mic/ligan License No.

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL **REVISED MAY 14, 1975**

REVISED JAN., 1983