ALLEGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

	-	Filing nequire	singuit of Act 14, with 12	5. S	
	For corners in				
	ALLEGAN	Located in:	Corner Code ≠≠		
	(County)		ľ	== ` · _	
				TETO	
	 Public Land Survey 	T <u>2N</u> R <u>13W</u>	<u>G_13</u>		
		T R	ALLEGAN	= 4	
		T R		下 11 2:33 作品。	
		T R		=	
	2. Property Controlling	S T R		- <i>E</i> 32	
والأفراضة فيقوا فيسا المحد	in Section	s T R	-		
BUHVEY &		s T R		Register of Deeds Stamp & File Number	
REMONUMENTAT	Niscellarieous	S T R		Register of Deeds Statis & Fire Number	
REMONORMENTA	Property in Sec.	3			
:		and a file			
	4. Lot No, Rec	corded Plat		- ABGDEFGHIJKL	
APR 2 9 1996	5. Private Claims			2 1 1 1 1 1 1 1 1 1	
111 11 12 12 12 1				3 1 1 1 1 1 1 1	
	.1		•		
COMMISSION	V			* - 7 8 9 10 11 12	
00,	IDOMALD K. PLITE OK.	in a field survey on	UULY 27 . 1995	· 5	
	do hereby certify that under requi	rements of P.A. 74. Michigan P.A.	of 1970, the corner points mentioned	5 6 10 17 10 15 14 13	
	In lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5				
	shove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a				
	Court of Law established re-	established, monumented, re-	nonumented, recovered, found a	s 9 	
	expressed below:			10 29 28 27 26 25	
	NOTE: Not more than 4 cor	ners all in the same town a	nd range may be recorded	11	
		ners, an in the same town o	in things, may be recovered	12 33 35 36 36	
	on this certificate.		•		
			dia airba arrest contentino:	13	
	Description of original monument and accessories and/or subsequent restoration:				
	·				
	G.L.O. SET POST				
	SUGAR 18 N31	E 30			
	SUGAR 24 N65	W 29			
	1983 COUNTY SURVEYORS NOTES SET 1/2" PIPE 5/9/83 (CONTINUED ON BACK OF CERTIFICATE) P.K. SW ROOT 27" HACKBERRY N50W 11.10' P.K. E SIDE 21" WALNUT N20W 19.94' P.K. E SIDE 5" HICKORY NORTH 6.03'				
	1/2" PIPE WEST 75.90'				
	B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:				
	FOUND 1/2" REBAR W/CAP "D.E.E. 29245"				
	N & T IN E OF 14" EIM S 25 E 44.30' N & T IN E OF 14" SYCAMORE S 10 W 33.93' N & T IN NE OF 12" EIM S 50 E 59.00 FEET PULLED REBAR AND SET STANDARD ALLEGAN CO. REMON 3/4" x 36" IRON W/RED CAP # 23520				
TRAVERSED 8070' WEST					
	APPROVED BY THE ALLEGAN CO. REMON PEER GROUP JUNE 13, 1995, AND IS ACCEPTED AS A				
	CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER APPROVED REMONUMENTATION CORNER				
	CARLE OF THE THERE OF			P.A. 345 OF 1990	
	-			ALLEGAN COLINTY	
				DATE APPROVED 6-13-95	
				COUNTY REP. Suit I Want The	
			•	•	
	C. Description of monument	for comer and accessories	established to perpetuate locat	ing the position of the corner:	
	G-1 TIN, RISW - STANL	ARD ALLEGAN CO. RENG	N. 3/4 X 30 LEON W/R	ED CAP # 23520 WEST 75.85'	
	FOUND 1/2" REBAR W/PI	ASTIC CAP "DEE 29245	•	OF MICE	
	N & T IN E OF 14" ELA	4 S 25 E 44.30'		(30)	
	N & T IN E OF 14" SYC	ZAMORE S 10 W 33.93'		DONALD R. T.	
	N & T IN NE OF 12" EIM S 50 E 59.00' PITTS, JR. \\				
				Land Surveyor	
				\\ \. \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
				No.	
				25867	
	-			Cored Land Sur	
	\rightarrow 1	10 1115	/ h/	DAGE	
•	Signed by Donald	1K.ITUL	Date 25	MUGUST 1775	
	•	No. 2586/		•	
	Surveyor's Michigan License	No		ru approved by michigan state marb of Lamo Surveybas, Jam. 28, 1 Beysser may 14, 1	
	ถกกะ	4 Oo curre	1 0= 2	Bevised Man., 1	
	UBER 0005 _{PM}	GE 182	1 OF 2		
		-			

(CONTINUED FROM FRONT OF CERTIFICATE)

A. 1994 - DAVID E. ERICKSON
L.C.R.C. LIBER 4, PAGE 388
SET 1/2" REBAR W/PLASTIC CAP "DEE 29245"
SET N & T IN E OF 14" ELM S 25 E 44.30'
SET N & T IN E OF 14" SYCAMORE S10E 33.93'
SET N & T IN NE OF 12" ELM S 50 E 59.00'
CAPPED IRON N.E. COR. SEC 4 N 85 W 75.90'
FOUND CAPPED IRON # 26463 NORTH 50.21'