## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in ALLEGAN		Located In:		Corres Code -44												
	(County)		Locale	ea m.		Corner Code ##										
1.	Public Land Survey		T _2	N A	15W 15W	H1H2	 									
	Property Controlling in Section Miscellaneous Property in Sec.	S S	T T T	R R		· · · · · · · · · · · · · · · · · · ·	- -   1	Register	of [	) eed:	s Sta	mp	& Fil	e Nı	ımbı	er
f, _do in cui Ma abi Co exp	BARY C. BILOW hereby certify that under red lines 1 and 2 above were in rrent manual of survey instrinagement or by a decree of ove were in conformance wi urt of Law; established, in oressed below:  OTE: Not more than 4 c	, in a fie quirement n conform uctions of a Court of th the rule re-establis	old survey s of P.A. 7 lance with the Unite Law and/ es of the N shed, mo	y on _ 74,Mic h regu ed Sta /or tha Michig onume	JANUARY chigan P.A ulations ar ates Depar at the corne an Board o ented, re-	, 19 . of 1970, the corner points ind rules therefore as requirtment of the Interior, Bureier points mentioned in lines of Land Surveyors or by a Emonumented, recovered,	91 , mentioned ired in the au of Land s 3, 4 and 5 Decree of a found as	2	B - 6 7 18 19 30	C [ ]		9 16 21 228 28	10 15		J K	12-13-24-25-
	on this certificate.  Description of original							12	31—	32		33	34		35	36-

- (H-1) CORNER NOT ESTABLISHED IN ORIGINAL SURVEY. SHOWN IN COUNTY SURVEYOR RECORD BY E.P. WATERMAN (1887) AS "60V. STAKE" 1.79 CHAINS WEST OF THE SOUTH 1/4 CORNER OF SECTION 34, T3N-R15N. NO DTHER ACCESSORIES NOTED. FOUND NO RECORD OF CORNER IN MICHIGAN DEPT. OF TRANSPORTATION FIELD NOTES FOR STATE HIGHWAY M-89. CORNER RECORDED BY D.A. RATEKIN, 1972 (LCRC LIBER 2, PAGE 60) AS FOUND 3/4" IRON IN MONUMENT BOX. RATEKIN NOTES OLD MONUMENT AND ACCESSORIES: BOAT SPIKE; 8" DAK N19E 84.12', 9" TWIN DAK N17H 41.46', 10" TWIN DAK S62N 94.60'.
- (H-2) CORNER NOT ESTABLISHED IN ORIGINAL SURVEY. SHOWN IN COUNTY SURVEYOR RECORD BY E.P. WATERMAN (1887) AS "STAKE". NO ACCESSORIES NOTED. CORNER RECORDED BY D.A. RATEKIN IN 1977 (LCRC LIBER 3, PAGE 207) AS 1/2" IRON.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - (H-1) FOUND AND ACCEPTED 1/2" DIA. PIPE IN MONUMENT BOX AT CENTERLINE OF HWY. M-89 AND CENTERLINE OF ROAD TO THE SOUTH. DLD TIE SHOWN ON RATEKIN'S LCRC CHECKS TO 14" TWIN DAK NW. ACCESSORIES TO DAK TREES SHOWN ON PREVIOUSLY RECORDED SURVEY (LIBER 1057, PAGE 720) ALSO CHECK.
  - (H-2) FOUND AND ACCEPTED 3/8" IRON BAR IN MONUMENT BOX. RATEKIN'S TIE TO 20" OAK (NON 24" OAK) CHECKS. DETERMINED THIS MONUMENT TO BE 1.07' WEST AND 1.51' SOUTH OF THE INTERSECTION OF STRAIGHT LINES CONNECTING OPPOSITE 1/4 CORNERS.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
  - (H-1) FOUND 1/2" IRON PIPE IN MONUMENT BOX
    N2OW 41.62' FD SPIKE EAST FACE 14" THIN DAK
    N65E 73.84' SET NAIL AND MONR TAG SE FACE 10" TRIPLE DAK
    S15M 91.37' SET NAIL AND MONR TAG EAST FACE 17" DAK.
  - (H-2) FOUND 3/8" IRON BAR IN MONUMENT BOX
    N35W 87.09" FD PK NAIL WITH TAG SW FACE POWER POLE
    S20W 108.36" SET NAIL AND MONR TAG EAST FACE 12" AND 17" TWIN DAK
    N80E 68.63" SET NAIL AND MONR TAG SOUTH FACE 24" DAK.
    SOUTH, 15" CENTERLINE OF EAST-WEST GRAVEL ROAD.



Signed by	C. Bilow	Date	3/8/91	
Surveyor's Michigan License No	26453		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURV	/EYORS, JAN. 28, 1971