CO


FOR CORNERS IN: LOCATED IN: **CORNER CODE # ALLEGAN COUNTY** T....T R...13W 1. Public Land Survey A-12 **WEST 1/4 CORNER** R..... SECTION 31, T.3N., R.13W T..... R..... MONTEREY TWP. T..... R..... 2. Property Controlling S......R..... in section S.....R..... 3. Miscellaneous S......R......

Property in Sec. 4. Lot No....,Recorded Plat....

5. Private Claims....

1, Raymond Moored in a field survey on Sept. 23, 1999 do hereby state that under requirments of P.A 74, Michigan P.A. of 1970, corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior Bureau of Land management or by a decree of a Court of Law and/or that the corner points mentioned in the lines 3, 4, and 5 above were in comformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law established, monumented, recovered, found as expressed below.

Note: Not more than 2 comers, all the same town and range, may be recorded on this certificate.



A.Description of original monument and accessories and/or subsequent restoration:

- 1. G.L.O. NOT ESTABLISHED BY G.L.O.
- 2. MITCHELL SURVEY'S INC., ACT 132 SURVEY, 4-19-79 1/2" IRON

-FENCE COR. POST -60" MAPLE NE NNW 40.82 SW 50.57 SOUTH 14.50 -16" PINE -HEATH CORNER

-A-12 EAST TO B-12 = \$89°-56°-00"E -A-12 NORTH TO A-11 = N01°-48°-40"W

3. KIRL L. VANORDER, ACT 132 SURVEY, 12-4-92

SET CAPPED IRON
-FD R.E.M. CAPPED IRON
-PK IN SE SIDE 24" SPRUCE
-NAIL IN SW SIDE 38" MAPLE W SW NAIL IN SE SIDE 16" SPRUCE SW PK IN NE SIDE TELE. POLE SE

4. RATEKIN SECTION CARD WEST 1/4 POST 24" MAPLE NE 41' IRON TORSION BAR 18" MAPLE SW 63' 33" MAPLE

NW 40.31 NW 55.9 20" EVERGREEN NW TELE CABLE MARKER W 55.4 52.7 EVERGREEN 18" MAPLE SE 63 92.0

(5-15-91) FD. REMAINS OF PREVIOUS CORNER PLACED 1/2" PIPE OVER

B.Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" IRON IN MON BOX 0.06' WEST OF RANGE LINE PER #2 & #3 ABOVE SET STANDARD ALLEGAN COUNTY REMON IRON WICAP IN PLACE OF FOUND CORNER ON RANGE LINE.

THIS POSITION NOT ESTABLISHED BY ORIGINAL GOVERNMENT SURVEYORS. THIS MONUMENT IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE CORNER.

APPROVED BY ALLEGAN COUNTY REMONUMENTATION PEER GROUP ON DEC. 14, 1999

TOTAL ON ROAD TRAVERSING = 2642.86'

C.Description of monument for corner and accessories established to perpetuate locating the position of the corner:

APPROVED REMONUMENTATION CORNER

SET 3/4" X 24" STANDARD ALLEGAN COUNTY REMON IRON WITH CAP IN MON BOX

-PK IN TOP OF CORNER FENCE POST N38E 58.61'

-PK IN SE SIDE 12" PINE S65W 52.35"
-PK IN NE SIDE P. POLE S22E 92.20"

-M-12, T3N, R14W. SOUTH 14.45

Surveyors License No. 26463

P.A. 345 OF 1990 ALLEGAN COUNTY

DATE APPROVED DEC. 14, 199 COUNTY REP.

