SUHVEY & REMONUMENTATION

APR 2 5 1995

COMMISSION

Property in Sec.

5. Private Claims ___

ALLEGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970		70 <u>≥</u> _∞ ≥ 3 ⁻²	鲁	
-	1	SISA Asc		T
ed in:	Corner Code ##	HER	ω	7
N a 15W	r-i		<u> </u>	'n
3N R 15W	N. 1/4 Cor.	Ø E	3	
	Sec. 4		$\dot{\gamma}$	0

For corners in ALLEGAN 1. Public Land Survey Manlius Twp. R 2. Property Controlling __ R in Section Register of Deeds Stamp & File Number R. s Miscellaneous

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

S ___ , Recorded Plat

•Corner not set by GLO
•J.W. Hicks survey drawing dated 11/1/1875 shows a stone at corner

•Allegan County Road Commission section corner information card:
Punch mark in E. end conc. culvert SE 65.64'
Punch mark in W. end conc. culvert SW 62.51' รพ 74.83 Punch mark in telephone pedestal 77.65' E,NE Iron

(Continued on back of sheet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Fd. 1" steel rod 11 1/2" long in mon. box 0.23' South of townline and 1.16' West of midpoint between E-1 & G-1. Corner was established using improper procedures and is not utilized in this survey. Set F-1 at a point midway between E-1 & G-1 on a line between E-13 & F-13 of T4N, R15W.

This position not established by original government surveyors. This monument is accepted as the best available evidence of the position of the corner.

Peer Group approved 3-9-94. Traversed 5407.07'. (on road)

APPROVED REMONUMENTATION CORNER
P.A. 345 OF 1990
ALLEGAN COUNTY
DATE APPROVED
3 - 9 - 9 + COUNTY REP.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set standard Allegan Co. Remon. monument (3/4" x 36" steel rod w/red cap #23520) AZ. 284° 187.81' Nail & Remon. tag in NE side Power Pole Nail & Remon. tag in NW side Power Pole SE corner concrete block building 155.17 AZ. 72° AZ. 349° AZ. 125° 234.17' Nail & Remon. tag in Power Pole Capped iron Fillmore corner 171.48' 151.61' East

12-30-94 Signed by

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1915 REVISED JAN., 1913

HEER0005page138

Page 1 of 2

10005 PAGE 139

Section A (continued from Page 1)

•Holland Engineering, Inc. set steel bar midway, not on line CL SS N,NW 21.00'
TP SW 70.98'
Fillmore corner East 151.69'

•K.V.O. survey 6-19-81 (81-12) shows 1" steel bar w/same ties
•K.V.O. survey 8-7-85 (85-638) shows 1 1/4" rebar in mon. box
w/different ties
•K.V.O. survey 4-11-91 (91-2381) shows other ties
•W-M survey 12-09-92 (92-958) shows 1" iron in mon. box with other
ties used

ties used
•No LCRC found

APPLANTED SOLVEN TENNESSENSE SOLVEN S