ALLEGAN COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	For corners in			元型の	3 3		
	Allegan	Located In.	Corner Code ≠#	<u> </u>	i e e		
	(County)			<u> </u>	= =		
	1. Public Land Survey	T 4N R 14W	н-10	글목	A .		
SUAVEY &	i. Public Land Sulvey	T R	Center	<u>73</u>	(. ⊒ મું		
	·imht	T R	Sec. 27	# [3			
REMONUMENTAL	IN SIX	T R	Overisel Twp.	÷			
	2. Property Controlling	s T R			% 3g		
155 0 0 4000	in Section	s T B			Die en Belle Herring		
APR 2 9 1996	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds	s Stamp & File Number		
	•						
COMMISSIO	N4. Lot No Red	corded Plat	·	A B C D) E F G H I J K L W		
00111111	5. Private Claims						
			Wareh 28 19 05				
	do horoby codyfuth at under reciti	I. Kirk I. Van Order, in a field survey on Harch 28 19.95 . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned to the corner poin					
	in lines 1 and 2 shove were in 6	conformance with regulations	and tules ineretore as required	m me [1] 1			
	current manual of survey instruct Management or by a decree of a	tions of the United States Dep Court of Lawand/or that the cor	ner points mentioned in lines 3, 4	and 5 8 19 20	22 - 23 - 24 - 24 - 24 - 24 - 24 - 24 -		
	about wars in conformance with	the cutes of the Michigan Boar	d of Land Surveyors of by a Decr	ee ora allit			
	Court of Law; established, re-	established, monumented, re	e-monumented, recovered, fou	nd as	28 26 25		
•	expressed below: NOTE: Not more than 4 cor	all in the come four	and range may be recorder				
	NOTE: Not more than 4 cor on this certificate.	ners, an in the same town	and range, may be received	12 -31 -32	2-33-34-35-35-36-		
	On this certificate.			13			
	A. Description of original m	onument and accessories a	and/or subsequent restoration	n;			
	H-10		•				
	eCTO did	not set					
	•MacDouga	ll survey record	ed May 11, 1905 i	ndicates stone	at corner		
	2690.2	to N 1/4 corner	Sec. 27		•		
		to E 1/4 corner to S 1/4 corner			The state of the s		
	2620.47	to W 1/4 corner	Sec. 27		E OF MICH		
	2020.4	20 11 27 2 002		4	Service 1		
			(cor	ntinued on back ϕ	of SHOORDER		
	B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:						
	H-10						
	Kirk T. V	an Order survey	Mar. 28, 1995	Y	100 1 23320 11 STE		
	Kirk L. Van Order survey Mar. 28, 1995 Fd. stone with depression in top with iron along side by us the gamen.						
	ties as s	tated in April 6	, 1984 survey		William Co.		
	Mhis posi	tion not establ	ished by origina	l government s	urvevors.		
	This position not established by original government surveyors. This monument is accepted as the best available evidence of the APPROVED REMONUMENTATION CORNER						
	position	of the corner.			NUMENTATION CORNER 345 OF 1990		
	•	3.0.5	10 1005	ALLE	GAN COUNTY		
	Peer grou	p approved Oct.	10, 1995.	COUNTY REP. 2	10-10-95		
	Distance	traversed: off	road = 5357.54'	on road = 5	260.20'		
	C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:						
	•						
	H-10 Removed s	tone and iron and	d set standard All	egan Co. Remon.	. monument		
	$(3/4" \times 3)$	0" steel ròd w/x	red cap #23520)	•			
•	Nail & Re	mon. tag in S si	de 24° Spruce	AZ. 79°26′	155.82'		
	Nail & Re	mon. tag in W si	ide power pole	AZ. 179°23′	36.62'		
	SW corner	conc. foundation	on to metal bldg.	AZ. 330°10′ AZ. 340°56′	199.30' 181.17'		
		ner Sec. 27	on to metal bldg.	N00°04'17"E	2689.54		
		mer Sec. 27		S86°25'16"E	2639.66'		
		mer Sec. 27		S00°02'55"W	2668.00'		
		ner Sec. 27	/	N86°23′50"W	2620.54		
•	07.1	1 Charles	Date _	12-13-95			
•	Signed by						
	Surveyor's Michigan License			FORM APPROVED BY MICHIGAN ST	TATE BOARD OF LAND SURVEYORS, JAN. 21, 19 REVISED MAY 14, 19		
	เลยใก้	105 _{page} 277	Page 1 of 2		REVISED JAN . 19		
		I NUL - I					

```
H-10

GLO did not set

MacDougall survey recorded May 11, 1905 indicates stone at corner 2690.2' to N 1/4 corner Sec. 27 2639.1' to E 1/4 corner Sec. 27 2668.2' to S 1/4 corner Sec. 27 2620.4' to W 1/4 corner Sec. 27
```

(continued on back of sheet)

H-10 Kirk L. Van Order survey Mar. 28, 1995 Fd. stone with depression in top with iron along side by using same ties as stated in April 6, 1984 survey

This position not established by original government surveyors. This monument is accepted as the best available evidence of the position of the corner.

Peer group approved Oct. 10, 1995.

Distance traversed: off road = 5357.54' on road = 5260.20'

<u>H-10</u>		
Removed stone and iron and set standard All (3/4" x 30" steel rod w/red cap #23520)	egan Co. Remon.	monument
Nail & Remon. tag in S side 24" Spruce Nail & Remon. tag in W side power pole	AZ. 79°26' AZ. 179°23'	155.82' 36.62'
SW corner conc. foundation to metal bldg. SE corner conc. foundation to metal bldg.	AZ. 330°10' AZ. 340°56'	199.30' 181.17'
N 1/4 corner Sec. 27 E 1/4 corner Sec. 27	N00°04'17"E S86°25'16"E	2689.54' 2639.66'
S 1/4 corner Sec. 27 W 1/4 corner Sec. 27		2668.001