ena Rounty Remonumentation Corner RECORDED LIFE Alpena ALPENA COUNTY HI. LAND CORNER RECORDATION CERTIFICATE comers in APR 08 199' DEC 12 9 31 AM '94 Filing Requirement of Act 74, Mich. P.A. 1970 Mariany a A. Johnston Located In: Corner Code ## 29N G-78E RECISTER OF DEEDS Public Land Survey \_\_\_\_ R \_\_\_\_ \_\_ R \_ R in Section \_\_\_ T \_\_\_ \_\_ T \_ Miscellaneous Register of Deeds Stamp & File Number Property in Sec. \_\_\_\_\_, Recorded Plat \_\_ Fi ⊟ Private Claims Earl T. Lewis July 22 , in a field survey on to hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as = xpressed below: INOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. -A. Description of original monument and accessories and/or subsequent restoration: Description of original monument and accessories and/or subsequent restoration:

(GLO) July 11, 1839, Lewis Glason set post, no monumentation given, witness given: Hem 24, 8 74 E, 32 / Cedar 9, N 75 1/2 W, 27

1892, Fred A. Rice, set stake, no witnesses given.

1905, Joseph W. McNeil, set cedar stake, no witnesses given.

1972, James L. Scott, P.S., found 1/2" rod, witnesses given: N 30° E 90.63' Power Pole / S 45° E 95.70' Tel. Pole

1978, D.R. MacNeill, P.S., set 1/2" re-rod, witnesses given: N 10° E 95.66' P. P. / S 10° E 108.90' P. P. / S 60° E 91.31' P. P.

1981, D.R. MacNeill, P.S., set 1/2" re-rod, wit. given: S 55° E 87.01' P. P. / S 25° E 107.54' P. P. / N 30° E 94.30' P. P.

1986, D.R. MacNeill, P.S., no monumentation or witnesses given (MacNeill makes reference to other existing 1/2" rod)

1993, D.R. MacNeill, P.S., no monumentation or witnesses given.

Description of corner evidence found and/or method applied in restoring or reestablishing corner: Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 1/2" rebar. ALSO; Found 1/2" rebar set by D.R. MacNeill, S 530 46' 43" E 8.55' from remonumented corner. P.A. 345 ALPENA COUNTY O Description of monument for corner and accessories established to perpetuate locating the position of the corner: 1994, Place Appropriately stamped Alpena County Remonumentation Aluminum Cap on existing 1/2" X 24" rebar in monument box, witnessed: S 30° E 114.20' Power Pole (found tag) S 70° E 96.10' Telephone Pole N 40° E 91.75' Power Pole (found tag EARL T N 55° E 51.00' Road Sign LEWIS 40° W 59.98' 1" Pipe ROFESSIONAL SURVEYOR

> FORM APPROYED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26. 1971 REVISED MAY 14, 1975

December 6,

Date

No. 27452

OFESSIO 1994\*\*\*

Surveyor's Michigan License No. .

Signed by Earl T.