LAND CORNER RECORDATION CERTIFICATE DE DUDITS Para 1151

For corners in "ECHO TWP"	Filing Requi	irement of Act 74, Mich. P.	A. 1970	
ANTRIM	Located in:	Corner Code #	amotes poin	eru wy
(County) 1. Public Land Survey	T <u>31N</u> R7W	<u>C-6</u>	HIRIM COUN Register of Recorded	
	TR TR TR		12-21-2000	11:09:29
2. Property Controlling S	Property Controlling S T R in Section S T R		Wanda R. Conway REGISTER OF DEEDS	
	· · · · · · · · · · · · · · · · · · ·		Register of I	Deeds Stamp & File Number
4. Lot No, Recorded Pla	ıt		ABCD	E F G H I J K L
5. Private Claims			2 6 5	4 3 2 1
			3	+
			4 - 7 - 8 -	9-10-11-12
I, NEILL WAY, in a support of P.A. 74, Michigal 2 above were in conformance with manual of survey instructions of the I Management or by a decree of a Court 4 and 5 above were in conformance with a Decree of a Court of Law; establishments of the I was a court of Law; establishments of the I was a court of Law; establishments of the I was a court of Law; establishments of the I was a court of Law; establishments of the I was a court of Law; establishments of the I was a court of Law; establishments of the I was a court of Law; establishments of P.A. 74, Michigal P.A. 1997, and P.A. 199	n P.A. of 1970, the con- egulations and rules the Jnited States Departme of Law and for that the the rules of the Mich	mer points mentioned in lines 1 herefore as required in the cur nt of the Interior, Bureau of L e corner points mentioned in line nigan Board of Land Surveyors o	and 6 10 0 17 or 1	
NOTE: Not more than 2 comers, all i	n the same town and r	ange, may be recorded	11	
on this certificate.			12 31 32	33 34 35 36
A. Description of original monument C-6 EAST 1/4 CORNER SEC. 18 GLO SET CORNER POST, A HI CHURCH, MAY 5, 1909, L 300, P 3 MARY FEINDT, MAY 27, 1976, L 2 LENNOX, SEPT. 18, 1984, L 290,	EMLOCK STAKE 3" S S 301, A STAKE, NO W 126, P 630 FOUND A 3	UGAR 28 N81 1/4W 21L UGAR 12 S79E 33L ITS OR DESCRIPTION. 3/4" IRON PIPE AT FENCE INT	REMI	SURVEY & ONUMENTATION JAN 23 2001
Description of corner evidence for	ound and/or method a	oplied in restoring or reestablisl	ning comer:	OFOTION
C-6 EAST 1/4 CORNER SEC. 18				SECTION
FOUND 3/4" IRON PIPE AT FENCE CO	RNER INTERSECTION T	O EAST, WEST AND SOUTH.		
 Description of monument for con C-6 EAST 1/4 CORNER SEC. 		stablished to perpetuate location	ng the position of the co	rner:
C-6 EAST 1/4 CORNER SEC. OF MICHIGATION NEIL L. WAY LAND SURVEYOR NO. 28432 OTAL SURVEYOR igned by	ACCEPTED REPLACED	3/4" IRON PIPE AS CORN WITH COUNTY MONUME N25E 17.54' MAPLE 16" 0W 25.67' MAPLE 6" TW S75E 23.96' MAPLE 12"		Ratified by Peer Group In accordance with P.A. 345 Antrim Co. Chairman
No. 28432 Colling Sylvery Sylv		SOUTH 15.44 MAPLE 14"		Arthur L. Lennox, P.E., P.S. Nov. 28, 2000
igned by	7		Date <u>DEC. 18, 2000</u>	<u></u>
urveyor's Michigan License No				