

**SURVEY &  
REMONUMENTATION**

**FEB 11 1998**

ANTRIM COUNTY MI.  
Register of Deeds  
Recorded

**LAND CORNER RECORDATION CERTIFICATE**

Filing Requirement of Act 74, Mich. P.A. 1970

12-02-1997 08:52:30

**CENTRAL LAKE**

**SECTION**

For corners in

ANTRIM  
(County)

Located In:

Corner Code #

Manda R. Conway  
REGISTER OF DEEDS

- 1. Public Land Survey SW T34N R34W E-9  
T\_\_\_ R\_\_\_  
T\_\_\_ R\_\_\_  
T\_\_\_ R\_\_\_
- 2. Property Controlling in Section S\_\_\_ T\_\_\_ R\_\_\_  
S\_\_\_ T\_\_\_ R\_\_\_
- 3. Miscellaneous Property in Sec. S\_\_\_ T\_\_\_ R\_\_\_  
S\_\_\_ T\_\_\_ R\_\_\_

Register of Deeds Stamp & File Number

124

- 4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
- 5. Private Claims \_\_\_\_\_

I, Terry B. Smith, in a field survey on 12-01, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

**A. Description of original monument and accessories and/or subsequent restoration:**

GLO Corner -- 4" Beech Post  
Sugar 11 N14E 15L  
Sugar 24 S14W 6

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

Survey by N. DeYoung 1976 -- apparently used incorrect corner (nail)  
Survey by Gosling Czubak, 1989  
Survey by L. Feindt 1978

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**


Found 1/2" bar & set Antrim County Monument  
12" Maple SOUTH 15.22  
14" Maple S50°E 7.63  
14" Basswood N05°W 22.18  
20" Ash N45°W 2.55

Ratified by Peer  
Group in accordance  
with P.A. 345  
Antrim Co. Chairman

*Arthur L. Lennox*  
Arthur L. Lennox

Nov. 18, 1997

Signed by Terry B. Smith  
Surveyor's Michigan License No. 25873



Date 12-01-1997

Liber 00002 Page 0408