

FEB 1 8 1994

COMMISSION

Arenac County Remonumentation

LAND CORNER RECORDATION CERTIFICATE

02 PAGE 007

	Filing Requi	rement of Act 74, Mich. P.A. 19	9 70	
For corners in				
Arenac	Located In:	Corner Code ++	DEC.	
(County)			SARI CARI	
1. Public Land Survey	T <u>18N</u> R <u>4E</u> T <u>18N</u> R <u>4E</u> T R T R	A-12 C-11	2 15 STEE COU	RECORDE
2. Property Controlling	S T R		PH	D
in Section	S T R		68 C	
3. Miscellaneous	S T R		ىت Register of Deeds Stamp & File	Number
Property in Sec.	S T R		Tregister of occus ofding a rine	
Craig W. McVean I, do hereby certify that under rein lines 1 and 2 above were current manual of survey inst Management or by a decree of above were in conformance w	Sept quirements of P.A. 74, Michigan P. in conformance with regulations a ructions of the United States Dep f a Court of Lawand/or that the cor with the rules of the Michigan Board	A. of 1970, the corner points mentioned and rules therefore as required in the artment of the Interior, Bureau of Land ner points mentioned in lines 3, 4 and 5 d of Land Surveyors or by a Decree of a e-monumented, recovered, found as	2 6 5 4 3 3 4 7 8 9 10 5 6 18 17 16 15 7 8 9 19 20 21 22 9	14 13 14 13 14 12 14 15 15 15 15 15 15 15 15 15 15 15 15 15
NOTE: Not more than 4	corners, all in the same town	and range, may be recorded	11	- - - -
on this certificate	. .		12 31 32 33 34	35 36
A. Description of original	I monument and accessories a	and/or subsequent restoration:	13	
A-12 Set post - L. Clas Pine 36" N 19° W 19 L. Hemiock 30" S 85° W 19	•	<u>C-11</u> Set post - J. Cedar 10" N 45° W		ing F. C. C.

W & S.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Distances N and S.

A-12 Standard 1/4 corner common to Sec. 31, T18N, R4E, and Sec. 36, T18N, R3E. Found remains of wood post, 2" diameter x 8" long, in sand layer 8" below gravel base of road. Agrees with occupation N, S, E, & W. Agrees with County surveyor distances S. Monument is accepted as a careful and faithful perpetuation of the position of the original corner. Accepted by Arenac County Peer Group on 12-8-93.

Bay County Surveyor - 1910 - G. Turner.

Arenac County Surveyor - Cedar Post, 1916.

C-11 Found 3/4" x 1' iron rod. Remove. Found 'L' angle iron below. Remove. Found 3/4" x 3' long iron pipe below per M.D.O.T. witness card. Fits County survey and M.D.O.T. distances S. Monument accepted as a careful and faithful perpetuation of the position of the original corner. Accepted by Arenac County Peer Review Group on 11-17-93.

County surveyor notes - RR iron. Distance and bearing ties

M.D.O.T. witness card - 1963 - L. 1, P. 211. Found 3/4" pipe

inside 1-1/2" angle iron 8" below road surface.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-12 Replaced wood post with 3-1/4" Bay-Arenac County brass cap on 5/8" rebar with 4" plastic drain tile sleeve and concrete in mon. box.

N 32° W 48.13' to nail and tag in SW side 12" Oak.

N 25° E 143.15' to nail and tag in SE side 36" Oak.

N 76° E 58.33' to nail and tag in NW side twin 8" Oak.

S 46° E 102.59' to nail and tag in SW side 12" Cedar.

S 56° W 184.65' to SE corner foundation House #5760.

C-11 Replaced rod, pipe, and angle iron with 3" Arenac County brass cap on 5/8" x 24" rebar in mon. box.

N 36° W 60.32' to SE corner concrete telephone pedestal pad.

S 48° W 72.47" to nail and tag in SE side U.P.

S 37° E 46.60' to 'x' on top concrete project marker.

N 21° W 65.35' to 'x' on top concrete project marker.

OF MICHIGAN CRAIG W. McVEAN PROFESSIONAL SURVEYOR Date No. 39088 80 OF LAND S Surveyor's Michigan License No. __ POFESSION